A all Plugs subject tocharge - No Info intile

Operator Weil Unit API #	Ready Cil : Gas Mingi Will Federal' # 10 <u>L</u> Section <u>13</u> Twiship <u>20</u> Ran 30-0 <u>15</u> -02365 <u>K</u> 60' Sunfan Aug	TOPS ge <u>78</u> Salade <u>~ 425'</u> Base <u>~ 650'</u> Yeites ~ 750'
	* Salt of g plug * Inst * Plug * Plug of c spe * Sho sho * Sun * Whi plac in th cen	tact OCD 24 hrs. prior to any work done. gel mud consisting of 10# brine with 25# el per barrel must be placed between each all dry hole marker as per Rule 202.B.2 gs are to be set from point indicated up. gs must not be less than 100' or 25 Sacks ement, whichever is greater, unless cifically indicated. e and stub plugs will be 50' above and below e or stub and tagged. face plug will be from 0' - 60' ere plugs are required, cement must be teed inside and outside of all casing string(s) ne correct footage or sacks required, if no nent exists. gs to be tagged will be indicated.
	< Plus tra	•