

Form 3160-5
(August 1999)

Oil Cons.
UNITED STATES N.M. DIV-Dist. 2
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
301 W. Grand Avenue
Alamogordo NM 88210

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

5. Lease Serial No.
NMLC 050797

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Ready Oil & Gas Management

3a. Address

P.O. Box 381 Artesia, NM 88210

3b. Phone No. (include area code)

505 746-4716

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

SE/NW Sec. 13, R. 20s Twp. 28c UT. F
1980 ENL 1980 FAX

8. Well Name and No.

Turner #4

9. API Well No.

3001502378

10. Field and Pool, or Exploratory Area

Russell

11. County or Parish, State

NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once reusing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Plug and Abandon AS Per OGD-BLM Procedures

A. Displace OPEN hole with mud as per OGD-BLM Spec.

B. Spot 25 Sack Cement Plug from 777' to 663' (25ct x 4.567' = 114')

C. ~~80~~ TAG Plug: Spot mud to 610'

D. Place ~~40~~ Sack Cement Plug from 610' to 438' to cover Salt (40ct x 4.567' = 182.67')

E. Place 80cwt mud to 60' After Tagging @ 438'

F. Set Surface Plug from 60' to 0'. Install Regulation P.A. marker

G. Remove electric service and RIP location.

APPROVAL SUBJECT TO
GENERAL REQUIREMENTS AND
SPECIAL STIPULATIONS ATTACHED

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

HE BULL DELAY

Title

Prop.

Signature

HE BULL DELAY

Date

12-18-02

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

(ORIG. SGD.) ALEXIS C. SWOBODA

Title

PETROLEUM ENGINEER DEC 30 2002

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

RECEIVED

2002 DEC 26 AM 9:04

BUREAU OF LAND MGMT
FISHHILL OFFICE