

New Mexico


Land Office LC 062254-A

Lease No. _____

Unit _____

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 26th

1957

Well No. 1-Mayfield is located 990 ft. from N line and 2310 ft. from E line of sec. 33
SE/4 33 20S 28E N.M.P.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Saladar-Yates Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3200 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On March 20, 1957, 143' of 7" casing was run at 145' and cemented with 10 sacks, water shut off was complete. Hole was then deepened to 699' where drill pipe broke 90' above bit. Hole has been idle since 4-9-57, after fishing operations failed to remove stuck pipe. It is planned to use special securing equipment on attempt to retrieve pipe, which is now being obtained, and is the cause for delay. Hole is presently shut in pending fishing attempts.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company George E. Conley, et al
Address P.O. Box 211 611
Santa Fe, New Mexico

By George E. Conley
Title Operator