

NEW MEXICO STATE LAND OFFICE
SANTA FE, NEW MEXICO
DEPARTMENT OF THE STATE GEOLOGIST

NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate. Following the completion of the plugging a report should be made under "Report on Result of Abandonment of Well" on Form SG-100.

F. J. Vesely

Roswell

May 7, 1935

_____, N. Mex., _____ 19____

Mr. _____

State Geologist,

George Etz et al

1 Santa Fe, New Mexico

36

20 S.

28 E

Dear Sir:

You are hereby notified that it is our intention to abandon **Edcy** Well

No. _____ in **36** T. _____, **35**

N. M. P. M., _____ Oil Field, _____ County.

We plan to commence work on **Structurally the well does not appear likely to produce oil or gas in commercial quantities.**

The reasons for wishing to abandon the well are as follows:

80'; 8 1/2" csg set at 330'. Total depth 785'. 10" csg set at
The present condition of the well is as follows:

The work which we propose to do in abandoning the well is as follows:

Pull all csg and fill with mud from 785' to 80'; Set a 10 sack cement plug at 80'; Fill with mud to the surface and erect a regulation marker. No salt was found in the well.

Approved MAY 1935 19____

Except as follows:

Sincerely yours,

George Etz et al

By _____

Company or Operator.

Position **Operator**

Send communications regarding this well to

Name **Neil H. Willis**

Address **Roswell, New Mexico**

F. J. Vesely
State Geologist or Oil and Gas Inspector.

NEW MEXICO STATE LAND OFFICE

SANTA FE, NEW MEXICO

DEPARTMENT OF THE STATE GEOLOGIST

NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate. Following the completion of the plugging a report should be made under "Report on Result of Abandonment of Well" on

32

May 1, 1917

Form SG-104

F. J. Vesely

1917 N. Mex.

Mr. State Geologist,
Santa Fe, New Mexico
Dear Sir:
You are hereby notified that it is our intention to abandon _____ Well _____ in _____ Co., N. M. P. M. _____ Oil Field. _____
The reasons for wishing to abandon the well are as follows:
We plan to continue work on _____
_____ the well does not appear likely to produce oil
_____ Oil Field, _____ Co., N. M. P. M. _____
No _____ in _____
You are hereby notified that it is our intention to abandon _____ Well _____
_____ Santa Fe, New Mexico
_____ State Geologist,
_____ Mr.

Total depth 785'. 10" csg set at

The present condition of the well is as follows:
80' 8" csg set at 730'.

The work which we propose to do in abandoning the well is as follows:
No hole was found in the well.
80' 8" will with mud to the surface and erect a regulation marker.
and fill with mud from 785' to 80'; set a 10 sec cement plug at
Total depth 785'. 10" csg set at

Sincerely yours,

George E. E. of A1

Company of Operator

By _____

Position Operator

Send communications regarding this well to

Name Well H. Wells

Address Roswell, New Mexico

State Geologist or Oil and Gas Inspector

Approved _____

Except as follows: