

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

RECEIVED
AUG 26 1993

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	B-2386 (Assng #2)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. (Well originally plugged and OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Re-plug (abandoned October 9, 1938)	7. Unit Agreement Name
2. Name of Operator Barber Oil, Inc. ✓	8. Farm or Lease Name State "A"
3. Address of Operator P. O. Box 1658 Carlsbad, NM 88221-1658	9. Well No. 2
4. Location of Well UNIT LETTER <u>H</u> , <u>1980'</u> FEET FROM THE <u>North</u> LINE AND <u>330'</u> FEET FROM THE <u>East</u> LINE, SECTION <u>19</u> TOWNSHIP <u>20S</u> RANGE <u>30E</u> N.M.P.M.	10. Field and Pool, or Wildcat Barber
15. Elevation (Show whether DF, RT, GR, etc.) 3257' (top of casing)	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASINGS <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Re-plug (see No. 1 above) <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER _____	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

TO BEGIN AS SOON AS APPROVAL IS ISSUED
Clean out existing well bore to a depth of 1280' (mostly mud). Cement well from 1280' to the surface and reset marker. (See well schematic attached) Clean location.

NOTE: All work to be directed by Eddy Potash, Inc. Contact is Mr. Bob Kirby or Mr. Jim Ryan. This work is being done at the request of Eddy Potash and Eddy has assumed all liability for the work. Barber will have personnel on hand to witness the work.

WITNESSED BY _____

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>President</u>	DATE <u>8/19/93</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>8/26/93</u>
CONDITIONS OF APPROVAL, IF ANY:		

STATE "A" No. 2
 UL-H, SEC. 19, T20S, R30E
 Eddy Co., NEW MEXICO

