

State of New Mexico  
Energy, Minerals and Natural Resources Department

Submit 3 Copies  
to Appropriate  
District Office

**DISTRICT I**  
P.O. Box 1980, Hobbs, NM 88240

**DISTRICT II**  
P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-015-04091

5. Indicate Type of Lease  
STATE  FEE

6. State Oil & Gas Lease No.  
B-2386 (Assign. #2)

7. Lease Name or Unit Agreement Name  
State "A"

8. Well No.  
2

9. Pool name or Wildcat  
Barber

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

2. Name of Operator  
Barber Oil, Inc.

3. Address of Operator  
P. O. Box 1658 Carlsbad, NM 88221-1658

4. Well Location  
Unit Letter H : 1980 Feet From The North Line and 330 Feet From The East Line

Section 19 Township 20 South Range 30 East NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3257' (top of casing)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <u>Reenter and replug</u>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9/23/93 - Set up on hole and started drilling with 12 1/2" bit. Lost circulation at 190'. Continued drilling to 231' and hit old 8-5/8" casing. Come out of hole.

9/24/93 - Welded 7' of 10-3/4" casing to 8-5/8" casing and ran into hole. Placed 10-3/4" pipe over top of old 8-5/8" casing.

9/27/93 - Pumped water in well and leveled out at 50'-60'. Ran into hole with 6 1/2" bit and got inside old 8-5/8" casing about 10'. Haliburton set 35 sax cement between old and new casing.

9/28/93- Plug holding water. Drilled out cement from 210'. Got into old casing and drilled down to plug at 314'. Drilled plug rest of day. Brass steel and cement returns.

9/29/93- Broke thru plug and continued down hole easily. Hit old 7" casing at 891' as reported.

9/30/93- Ran tubing and collars into hole and got into 7" casing about 5' and came out of hole. Haliburton placed 200 sax to 640'

10/1/93- Pumped another 200 sax and let set. Mixed 230 sax and filled to surface.

10/4/93- Set marker and cleaned location

all work done under the supervision of Eddy Potash c/o Bob Kirby (505) 887-2844

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE President DATE 11/8/93

TYPE OR PRINT NAME Michael D. Carringer (505) 887-2566 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY  
MIKE WILLIAMS  
SUPERVISOR, DISTRICT II

DATE NOV 22 1993

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_