

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Barber Oil Inc.	8. Farm or Lease Name Morris-Hoover
3. Address of Operator 901 West Pierce Carlsbad, New Mexico	9. Well No. 2
4. Location of Well UNIT LETTER L 2310' FEET FROM THE South LINE AND 990 FEET FROM THE West LINE, SECTION 20 TOWNSHIP 20South RANGE 30East NMPM.	10. Field and Pool, or Wildcat Barber
15. Elevation (Show whether DF, RT, GR, etc.) 3214 DF	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOE <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

(this report is filed to correct the prior report of 3- 5-62 on Morris-Hoover #1, located 1980' FNL, 660' FNL, Section 20, T.20S., R.30E., filed in error.)
Total finish depth of hole 1507. 8 5/8" casing cemented with 50 sax at 406';
6 5/8" casing cemented with 50 sax at 1397'. Plan to knock off 7" casing at about 800' and pull. Plan to knock off 8 5/8" casing at about 200' and pull. Will then run 2" tubing to bottom and cement hole to surface (if possible) or to a point in the 8 5/8" casing by Powell with about 500 sax. Will then cement in surface marker and clean grounds.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>John L. Ly</i></u>	TITLE President	DATE 1-18-66
APPROVED BY <u><i>M. L. Armstrong</i></u>	TITLE M. L. Armstrong	DATE JAN 21 1966
CONDITIONS OF APPROVAL, IF ANY:		