

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

100-443887-1

C. D.

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Re-plug (on August 14, 1947)		7. Unit Agreement Name (originally plugged and abandoned)	
2. Name of Operator Barber Oil, Inc. ✓		8. Farm or Lease Name Morris & Hoover	
3. Address of Operator P. O. Box 1658 Carlsbad, NM 88221-1658		9. Well No. 1	
4. Location of Well UNIT LETTER <u>E</u> <u>1980'</u> FEET FROM THE <u>North</u> LINE AND <u>660'</u> FEET FROM <u>West</u> LINE, SECTION <u>20</u> TOWNSHIP <u>20S</u> RANGE <u>30E</u> NMPM.		10. Field and Pool, or Wildcat Barber	
15. Elevation (Show whether DF, RT, GR, etc.) 3240(top of casing)		12. County Eddy	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: | SUBSEQUENT REPORT

PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER _____ <input type="checkbox"/>
OTHER <u>Re-plug (see No. 1 above)</u> <input type="checkbox"/>		ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. TO BEGIN AS SOON AS APPROVAL IS ISSUED.

Clean out existing well bore to a depth of 1200'. Well is reported to be cemented from 1421' to 400'. 400' to surface is mud. Cement well from a depth of 1200' to surface and reset marker. Clean location. (See schematic attached)

NOTE: This well is being replugged at the request of Eddy Potash, Inc. All work is to be directed by Eddy Potash and Eddy has assumed all liability for the work. Contacts with Eddy Potash are Mr. Bob Kirby and Mr. Jim Ryan. Barber will have personnel on hand to witness the work.

How long will it take you to witness


I hereby certify that the information above is true and complete to the best of my knowledge and belief.

* SIGNED Richard D. Gray TITLE President DATE 8/19/93

19-00000
TITLE OLAND GAS INSPECTOR DATE 8/26/93

CONDITIONS OF APPROVAL, IF ANY:

MORRIS & HOOVER No. 1
 U.L.-E, SEC. 20, T20S, R30E
 EDDY CO., NEW MEXICO



■ ORIGINAL CEMENT SETTING CASING

■ ORIGINAL PLUG/CEMENT

■ ORIGINAL PLUG/MUD

PROPOSED PLUG CEMENT