

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN 1
(Other instructions
on reverse side)

LICATE*

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 029009 (A)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Gatty Deep Unit

8. FARM OR LEASE NAME

Federal Enlay Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Gatty Deep (Harrow)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

24-208-298

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

GR 3310'

12. COUNTY OR PARISH

Bddy

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9-18- Pumped 30 sacks plug down 2-3/8" tubing, bottom at 12,229; top 11,979. Pumped 30 sacks plug down 2-3/8" tubing, bottom 10,815; top 10,565'.

9-20- Shot 7" casing as follows: 9,137; 9,041; 8,538; 8,505; and 8,001. Pulled 193 joints 29 H-80 X-line, 329 8rd H-80 casing. Run 2-3/8" tubing to 8,047'. Circulated mud. Set 100' plug in shot off 7" casing with 30 sacks cement. Bottom 8,047'; top 7,947'. Pulled 2-3/8" tubing up to 5,996', set 100' plug with 30 sacks cement. Bottom 5,996'; top 5,896'. Pulled 2-3/8" tubing to 3,726'. Set 100' plug in base 9-5/8" casing, with 40 sacks cement. Bottom 3,726'; top 3,626'. Pulled 2-3/8" tubing to 1,011'. Set 934' plug in 9-5/8" casing to cover salt solution with 240 sacks cement. Bottom 1,011; top 77'. Pulled 2-3/8" tubing. Set test sack plug in surface pipe. Welded steel cap. Installed marker and plugged and abandoned 9-27-67. See attached plat.

RECEIVED
OCT - 31967
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Production Foreman

DATE

September 28, 1967

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary specific instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking for approval of the abandonment.