CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

asi

DISTRICT I	OIL CONSERVA	ATI(ON DIVISION	C		
P.O. Box 1980, Hobbs, NM 88240	2040 Pacheco St.			WELL API NO. 30-015-10060	•	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210			7505	sIndicate Type of Le		
T.S. Diavel DD, Altesia, NW 00210				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	STATE	FEE
DISTRICT III 1000 Rio Brazos Rd., Azlec, NM 87410				₅State Oil & Gas Lease No.		
				V-4322		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"				rLease Name or Unit Agreement Name		
Type of Well:	-101) FOR SUCH PROPOSALS.	.)		Rookie State	e	
OIL GAS WELL MELL	OTHER					
Name of Operator Penwell Energy, Inc.				₅Well No. 1		
Address of Operator 600 N. Marienfeld, Suite 1100, Midland, TX 79701				Pool name or Wildcat Undesignated Bone Spring		
Well Location	iarid, 17 79701			Ondesignated	Some Spring	
Unit Letter B : 150	Feet From The North		Line and2056	Feet From The	East	Line
Section 7	Township 22S	F	Range 26E	NMPM	Eddy	County
	₀Elevation (<i>Show wheth</i> 3662' GR	er DF,	RKB, RT, GR, etc.)			
11 Check Ap	propriate Box to Indicat	te Na	ature of Notice, Rep	ort, or Other [)ata	
NOTICE OF IN	TENTION TO:		SUBS	EQUENT RE	PORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	X	REMEDIAL WORK		ALTERING CASI	NG
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING OPNS. PLUG AND ANBANDONMEN			NDONMENT
PULL OR ALTER CASING			CASING TEST AND CEME	ит ЈОВ		t _ 1
OTHER:			OTHER:			[-
12Describe Proposed or Completed Operations	s (Clearly state all pertinent details, a	nd give	pertinent dates, including est	imated date of starting	any proposed	
work) SEE RULE 1103. ROOKIE STATE #1			-	-		
1. Run tubing to 2630'.						
2. Load Hole with 75 bbls. gelled b	rine.					
3. Spot 25 sx. cement 2410' - 2630	0', above perfs 2638' - 2646' 8	& acro	oss shoe @ 2585'. WO	C. Tag Plug.		
4. Cut 5 1/2" csg. @ 1800' and put	ll					
5. Spot 25 sx. cement 1730' - 1890 6. Spot 40 sx. cement 65' - 175'. \	∂' @ top of csg. stub.		730 1- 1-9	10-780		
6. Spot 40 sx. cement 65' - 175', \	NOC. Tag plug.	501	you plug of			
7. Spot 5 sx. cement 3' - 10".¥ /0	sx sostace plug.					
8. Cut off wellhead 3' BGL. Cap w I hereby certify that the through continuous is the second continuous control of the second contro	/1/4" steel plate. * Notife	10 1	VMOCO. TO WIT	ness Pluggin	: Operation	1,
SIGNATURE SIGNATURE	rue and complete to the best of my k		ge and belief. LE Engineer		/ / DATE 07-29-	
TYPE OR PRINT NAME / SUSSE	u Lo. Core	Er	T		TELEPHONE NO. 6	415- 83-2534
(This space for State Use)						
APPROVED BY DOBRE STUPPER	.00	TIT	as Field Rea It		2175 AL 0	i/- 5 ¥