

INDIAN BASIN WELL NO. 2-1

3-6-1963

Stripped B.O.P. & spools out of cellar. Flanged up Xmas tree. Rigged Otis up and ran gauge ring. Went in & set plug in Otis seating nipple. Couldn't get off tool. Dropped cutter bar & cut Otis line off. Rigged up pulling unit & went in & got setting tool. Went in w/Otis tool & opened sleeve. Spotted 2000 gal acid, 15%. Went in & closed Otis sleeve & pulled prong from P.J. plug. Couldn't fish plug out. Left plug in thg. 17/32" hole in plug.

3-7-1963

Treated Upper zone w/2000 regular acid, 15%. Treated @ 42000. Did not break down. Ran suab 5 times & well kicked off & flwd. acid wtr back & died. Went back in w/suab. Subg. off seating nipple. Subg. thick black mud about 1/2 to 2/3 bbl. per run. Subd. Lower zone off. Ran suab 3 times & well kicked off @ 5:00 A.M. After well cleaned up made 13,200,000 CFTD w/3500 thg pressure.

5:00 - 6:00	12,800
7:00	13,200
8:00	13,200
9:00	13,200
10:00	13,200
11:00	13,200

SIF 31500

Re-treated Upper zone w/2000 gal mud acid, 15%. Treated @ 44000. ISUP 26000. In ten (10) minutes broke back to 12000. Didn't have to suab it. After it cleaned up making approx. 8,000,000 CFTD.

3-8-1963

Flwd. well 15-1/2 hrs. to clean & test same. 8,500,000 w/a spray of wtr. sulf. SIF 25500.

