

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL No. **LC067832-A**

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

West Indian Basin

8. FARM OR LEASE NAME

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Indian Basin Upper Penn

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

20, T21S, R23E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Oryx Energy Company ✓

3. ADDRESS OF OPERATOR

P.O. Box 26300, Oklahoma City, O.K. 73126-0300

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below)  
At surface

G, 1980' FNL & 1650' FEL

SEP 27 1991

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3991' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

7/3/91 MIRU X-pert WS. Prep to Kill well.

7/4/91 Kill well w/ 10 ppg brine/ ND tree & NU BOP/ rlse pkr & toh w/ tbg & pkr  
TIH w/ 3-7/8" OS w/ 7/8" grapple on 2-3/8" tbg to 6985' SDFN.

7/5/91 Shut down for holidays

7/6/91 FIH & tag @ 7242'/ attempt to latch fish/ TOH w/ tbg & tools. Rec iron sulfide  
but not fish/ TIH w/ 3-1/2" shoe w/ bulldog bailer/ TAG & cln out frm 7242 to  
7247'/ SDFN.

7/9/91 Kill well w/ 2% KCL wtr/ TOH w/ shoe & bailer/ TIH w/ 1 jt 3-13/16" WP on  
2-3/8" prod tubg/ wash over fish 7246-82'/ TOH w/ wp, rec 3' of wire/ TIH  
w/ 3-7/8" OS w/ 1-3/8" grapple/ Tag & latch fish/ TOH w/ 6 stds/ SDFN.

7/10/91 POOH. Rec fish/ RIH w/ baker Model "R" pkr on 2-3/8" prod tbg.  
Set @ 7278'/ Swab 1 hr. Rec 12 blw. FL 4100-7000'/ Check 2 hr FE. No FE  
Reset Pkr @ 6992'/ ND BOP. NU Wellhead/ SDFN.

7/11/91 Swab 10 hrs. Rec 0 BO, 142 BLW. FL 4100' & stable. Strong blow of gas. SDFN.

7/12/91 SITP 450 psi. Bled down to 0 in 15 min/ Swab 10 hrs. Rec 0 BO, 153 Blw.  
FL 4100-2800' w/ very strong gas blow. SWI & SDFN.

7/13/91 SI tbg press 1150 psi/ flow well 1 hr. Tbg press 1150-0 on 3/4" chk. Rec 0 bo,  
8 blw / flow & swab well 10 hrs, rec 0 BO, 82 blw, FL 2800-2150'/ Shut-in/  
Rig down & RR 7:30 pm 7/12/91. All load recovered.

Hook up to compressor. Evaluating w/o.

18. I hereby certify that the foregoing is true and correct

SIGNED

Jan Stevenson

TITLE Proration Analyst

DATE Sept. 18, 1991

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

SEP 20 1991

DATE

\*See Instructions on Reverse Side

25 1991

SJS