

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1-
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator <b>Hondo Oil &amp; Gas Company</b>		8. Farm or Lease Name <b>Hondo Singer</b>
3. Address of Operator <b>P. O. Box 1978, Roswell, New Mexico</b>		9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>B</b> <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>1980</b> FEET FROM THE <b>East</b> LINE, SECTION <b>18</b> TOWNSHIP <b>20-S</b> RANGE <b>27-E</b> NMPM.		10. Field and Pool, or Wildcat <b>Wildcat (Cisco)</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3333' Ground</b>		12. County <b>Eddy</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP at 7900'. Capped w/2 sx (17') of cement. Shot off 5-1/2" casing at 6348' and recovered same. Set the following neat cement plugs w/9# Gel mud between plugs:

30 sx 6360-6290  
40 sx 4750-4650  
30 sx 3162-3079  
30 sx 500-425  
10 sx In top of casing.

Both 13-3/8" & 9-5/8" casing strings were left intact. A dry hole marker was erected. I will notify you by letter when the location is ready for inspection.

RECEIVED

MAR 1 1965  
OIL FIELD  
ADMINISTRATIVE OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *A.D. Fletcher* TITLE Dist. Drilling Supervisor DATE 2-26-65

APPROVED BY *W.A. Gressett* TITLE OIL AND GAS INSPECTOR DATE OCT 15 1965

CONDITIONS OF APPROVAL, IF ANY: