

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other RE-ENTRY	5. Lease Designation and Serial No. NM-78213
2. Name of Operator YATES PETROLEUM CORPORATION (505) 748-1471	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. 105 South 4th St., Artesia, NM 88210	7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 990' FSL & 2310' FEL of Section 3-T22S-R24E	8. Well Name and No. Walt Canyon AMA Fed #1
	9. API Well No. 30-015-10305
	10. Field and Pool, or Exploratory Area Wildcat
	11. County or Parish, State Eddy County, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Commence operations, casing, perforations
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water
(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

CONTINUED FROM PAGE 1:

TIH w/wire filled cut lip shoe, wash pipe, drill collars, tubing, perforated sub to 7840'. Drilled to 7844'. TOOH. Caught 1 cone. TIH w/shoe with diamond and wire inserts, wash pipe, drill collars and tubing to 7844'. Drill and wash cement down to 7942'. TOOH and TIH w/bit, drill collars and tubing to 7942'. Drilled out cement to 7958'. Reversed hole clean. TIH w/bit, string mill and tubing. Work string mill through slip joint. TOH. TIH with bit, scraper and tubign to 7958'. Displaced hole with 2% KCL water. TOH. TIH w/logging tools. Could not get past 6954'. TOOH & TIH w/string mill. Worked thru tight spot at 6954'. TOOH. TIH w/logging tools and ran logs. TOOH & TIH w/packer and tubing to 7530'. WIH and prforated 7942-46' w/10 .42" holes (2 SPF). Spotted 2 barrels 20% NEFE acid. Set packer at 7788'. Acidized perforations 7942-7946' w/1500 gallons 20% NEFE acid and ball sealers.

14. I hereby certify that the foregoing is true and correct

Signed Rusty Klein Title Production Clerk Date May 20, 1993

(This space for Federal or State office use)

Approved by _____ Title _____ Date _____
Conditions of approval, if any: