	IL CONS COMMISSION ar DD
During 1990) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDERY NOTCES AND REPORTS ON WELLS Do not use this form for proposals of chill or to deepen or reentry to a different reservoir.	er DD sia, NM 88210 FORMAPPROVED
BUREAU OF LAND MANAGEMENT SUPPRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a drifferent reservoir.	Budget Bureau No. 1004-0135
SURDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.	Expires: March 31, 1993
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT -" for such proposals provide TSD SUBMIT IN TRIPLICATE 1. Type of Wall SEP = 5.94 2. Name of Operator Misrathon Cill Company 3. Address and Talephone No. P.O. Box 652, Midland, TX 78702 915/882-1826 4. Locatian of Wall (Bodge, Sec., T. R., M., of Surry Description) UL "F", 1860' FNL 81650' FWL SEC. 26, T-21-S, R-23-E 12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT. TYPE OF SUBMISSION TYPE of ACTION Notice of Index Abandonment Abandonment Notice of Index Abandonment Abandonment Subsequest Report Phaging Back Calege Repair 3. Describe Propond or Completed Operatione (Clearly state all pertinent detail, and give pertinent deta, including estimated data of and give Refutive besidem and measured and rever vertical detail, and give pertinent deta, including estimated data of and give Refutive besidem and measured and rever vertical details and give pertinent deta, including estimated data of and give Refutive besidem and measured and rever vertical details and the work. The Diverse of a state of and give Refutive besidem and measured and rever vertical details for all anatorice and state work. The Diverse of a state of the test of the diverse of the work. The Diverse of the diverse of the work. The Diverse of t	5. Lease Designation and Serial No.
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT -" for such proposals provide 1000 SUBMT IN TRIPLICATE 1. Type of Wall 3. Address and Tabyton NO. P.O. Box Seb2, Midland, TX 79702 916/682-1626 4. Locking of Wall (Potage, Sec., T. R. K., or Survey Description) UL, "F", 1860' FNL & 1660' FNL 5. Address and Tabyton NO. P.O. Box Seb2, Midland, TX 79702 916/682-1626 4. Locking of Wall (Potage, Sec., T. R. K., or Survey Description) UL, "F", 1860' FNL & 1660' FNL SEC. 26, T-21-S, R-23-E 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT. TYPE OF SUBMISSION TYPE OF ACTION Notice of Islam Abandoamset X submquast Report Data data data data data data data data	NM-070522-A
Use "APPLICATION FOR PERMIT -" for such proposals or control SUBMIT IN TRIPLICATE SUBMIT IN TRIPLICATE 1. "pro of Wall SEP = 0.194 2. "Ame of Operator SEP = 0.194 3. Address and Trisphons No. P.O. Box 582, Midland, TX 79702 915/682-1626 Advance of Wall (Produce, Sec. T. R. M. or Surrey Description) U. F*, 1650' FNL & 1650' FWL SEC. 28, T-21-5, R-23-E Interview Mail (Produce, Sec. T. R. M. or Surrey Description) U. F*, 1650' FNL & 1650' FWL Sec. 28, T-21-5, R-23-E Interview Mail (Produce, Sec. T. R. M. or Surrey Description) U. F*, 1650' FNL & 1650' FWL Sec. 28, T-21-5, R-23-E Interview Mail (Produce, Sec. T. R. M. or Surrey Description) UL F*, 1650' FNL & 1650' FWL Sec. 28, T-21-5, R-23-E Interview Mail (Produce, Sec. T. R. M. or Surrey Description) Very of SubMission TYPE OF SUBMISSION TYPE OF SUBMISSION Other Fredocolspan="2">Other Produce Sec. 20, DEC Other SubMission Other Fredocolspan="2" <td>6. If Indian, Allottee of Tribe Name</td>	6. If Indian, Allottee of Tribe Name
SUBMT IN TRIPLICATE 1. Type of Well	
Check appropriate the set of	7. If Unit or CA, Agreement Designation
2. Name of Operator Marathon OI Company Address and Telephone No. P.O. Box 552, Midland, TX 78702 915/682-1626 4. Lostion of Wall (Pooles, Sec. T., E., M., or Survey Description) UL "F", 1650' FNL 8 1650' FWL SEC. 26, T-21-S, R-23-E 2. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT TYPE OF SUBMISSION TYPE OF ACTION Notice of Issest Boundary and the pool Plaging Back Cating Back Boundary Country and an analysis of the sector of the	-
Marathon Ol Company 915/682-1626 3. Address and Telephone No. 915/682-1626 4. Location of Well (Pootage, Se., T., R., M., or Survey Description) UL "F", 1650' FNL & 1650' FWL SEC. 26, T-21-S, R-23-E	8. Well Name and No.
Address and Takephone No. P.O. Box 552, Midland, TX 79702 915/582-1825	INDIAN BASIN C 1
P.O. Box 552, Midland, TX 79702 915/682-1626 4. Lossion of Wall (Poolage, Sec., T., R., M., or Survey Description) UL "F", 1650' FNL \$1650' FNL \$1650' FNL \$250.26, T-21-S, R-23-E 2. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, TYPE OF SUBMISSION TYPE OF ACTION 2. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, TYPE OF SUBMISSION TYPE OF ACTION 3. Notice of Interat Abaadonmeet Will Subsequent Report Recompletion Will Subsequent Report Cating Repair Abaadonmeet Notice Abaadonmeet of this work.)* Observice browned or Completed Operations (Clearly state all pertiseed details, and give pertisent dates, including estimated date of star give solutions and measured and true vertical deptah for all matcher and mose to this work.)* 06-16-94: MIRU PU, ND TRE. NU & TEST BOP. POOH W/TBG & PKR. PERF SOZ HO JSPF. SET RITTS PKR @ 7433'. PUMP MARASEAL POLYMER AS FOLLOWS: 240 BBL BBL 50,000 PPM MARASEAL X-LINK GEL & 13 BBL FRESH WTR FLUSH. LET SET OVER PKR. RH W/2 7/8 PROD TBG. LOAD BACKSDE W/TR FLUSH. LET SET OVER KK. 1000 PSI. ND BOP. NU TREE. RDMO. WAIT ON POLYMER SET 7 DAYS. RU SWAB UN FLOWED WELL TO WORK, SI MGH WATER PRODUCTION. TEST PRIOR TO WORK, SI MGH WATER PRODUCTION. TEST PRIOR TO WORK, SI MGH WATER PRODUCTION. TEST AFTER WORK, O BO, 695 MCF, 132 BW DAILY 4. Lareely certify the tab foregoing is true and centred ADV. ENGIN. TECH. Signed ADV. OR Sign OF TABLE ST <td>9. API Well No. 30-015-10332</td>	9. API Well No. 30-015-10332
UL TF*, 1850' FNL & 1850' FWL SEC. 28, T-21-S, R-23-E 2. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, TYPE OF SUBMISSION Image: Submission in the set of t	10. Field and Pool, or exploratory Area
SEC. 26, T-21-S, R-23-E CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, TYPE OF SUBMISSION TYPE OF SUBMISSION Average of latent Subsequent Report Type of latent Subsequent Report Subsequent Repo	INDIAN BASIN/UPPER PEN
TYPE OF SUBMISSION TYPE OF ACTION Noice of Issest Abadonmeet Mice of Issest Recompletion Mice of Issest Recompletion Plagging Back Casing Repair Abadonmeet Casing Repair Abardonmeet Notice Abardonmeet Casing Describe Proposed or Completed Operations (Charty state all pertinent details, and give pertinent dates of starger without and measured and true writted deplat for all markers and zones pertinent to this work.)* OB-16-94: MIRU PU. ND TRE. NJ & TEST BOP. POOH W/TBG & PKR. PERF SOZ MO JSPF. SET RITS PKR @ 7433'. PUMP MARASEAL POLYMER AS FOLLOWS: 240 BBL BBL 60,0000 PPM MARASEAL X-LINK GEL & 13 BBL FRESH WTR FLUSH. LET SET OVE PKR. RIM W/2 7/8" PROD TBG. LOAD BACKSDE W/CHEMICALLY N#BITED 2% KCL." 10000 PSI. ND BOP. NU TREE. RDMO. WAIT ON POLYMER SET 7 DAYS. RU SWAB UN FLOWED WELL TO FRAC TANK. TEST PRIOR TO WORK, SI HGH WATER PRODUCTION. TEST AFTER WORK, O BO, 696 MCF, 132 BW DAILY 4. I baredy certify that the foregoing is true and correct Signed Monocompleteret Signed Monocompleteret Signed Monocompleteret Title ADV. ENGIN. TECH. (This space for Federal or State office usp) Title	11. County or Parish, State
TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Motice of Intent Abandonment Motice of Intent Recompletion Plugging Back Casing Repair Abandonment Notice Abandonment Notice Describe Proposed or Completed Operations (Charly state all pertinent details, and give pertinent datas, including estimated data of star give aubaurface locations and measured and true vertical deplat for all martiert and zones pertinent to this work.)* OB-16-94: MIRU PU, ND TRE. NJ & TEST BOP. POOH W/TBC & PKR. PERF SOZ MO JSPF. SET RTTS PKR @ 7433". PUMP MARASEAL POLYMER AS FOLLOWS: 240 BBL BBL 60,000 PPM MARASEAL X-LINK GEL & 13 BBL FRESH WTR FLUSH. LET SET OVE PKR. Rith W/2 7/8" PROD TBG. LOAD BACKSDE W/CHEWCALLY N#BITED 2% KCL. 1000 PSI. ND BOP. NU TREE. RDMO. WAIT ON POLYMER SET 7 DAYS. RU SWAB UN FLOWED WELL TO FRAC TANK. TEST PRIOR TO WORK, SI HGH WATER PRODUCTION. TEST AFTER WORK, O BO, 695 MCF, 132 BW DAILY 4. I bereby certify fat the foregoing is true and correct Signed Motice of redestal or State office usb)	EDDY COUNTY NM
Abasdonment Abasdonme	, OR OTHER DATA
Subsequent Report Beccompletion Subsequent Report Beccing Repair Bec	
Subsequent Report Bund Abandonmont Notice Final Abandonmont Notice Print Abandonmont Notice Berribe Proposed or Completed Operations (Clearly state all pertiased details, and give pertiased dates, including estimated date of star give subsurface locations and measured and true vertical depths for all marters and zoney pertinent to this work.)* 06-16-94: MIRU PU, ND TRE. NU & TEST BOP, POOH W/TBG & PKR, PERF SQZ HO JSPF. SET RTTS PKR @ 7433'. PUMP MARASEAL POLYMER AS FOLLOWS: 240 BBL BBL 50,000 PPM MARASEAL X-LINK GEL & 13 BBL FRESH WTR FLUSH. LET SET OVE PKR, RiH W/2 7/8' PROD TBG. LOAD BACKSIDE W/CHEMICALLY INHERTED 2% KCL., 1000 PSI, ND BOP. NU TREE, RDMO, WATT ON POLYMER SET 7 DAYS. RU SWAB UN FLOWED WELL TO FRACT TANK. TEST PRIOR TO WORK, SI HIGH WATER PRODUCTION, TEST AFTER WORK, 0 BO, 695 MCF, 132 BW DAILY 4. I bereby certify fat the foregoing is true and correct Signed	Change of Plans
Final Abandonment Notice Final Abandonment Notice Final Abandonment Notice Gaing Ropair Attering Casing OtherPOLYMER SQUEEZE Other	New Construction
Final Abandonment Notice Attering Cusing OtherPOLYMER SQUEEZE OtherOTHER Other	Non-Routine Fracturing
Allering Casing Other	X Water Shut-Off
Describe Proposed or Completed Operations (Cherly state all pertinent details, and give pertinent dates, including estimated date of star give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* O6-16-94: MIRU PU. ND TRE. NU & TEST BOP. POOH W/TBG & PKR. PERF SQZ HO JSPF. SET RTTS PKR @ 7433'. PUMP MARASEAL POLYMER AS FOLLOWS: 240 BBL BBL 50,000 PPM MARASEAL X-LINK GEL & 13 BBL FRESH WTR FLUSH. LET SET OVE PKR. RH W/2 7/8' PROD TBG. LOAD BACKSDE W/CHEMICALLY INHEITED 2% KCL. 1000 PSI. ND BOP. NU TREE. RDMO. WAIT ON POLYMER SET 7 DAYS. RU SWAB UN FLOWED WELL TO FRAC TANK. TEST PHOR TO WORK, SI HIGH WATER PRODUCTION. TEST AFTER WORK, O BO, 695 MCF, 132 BW DAILY . I bereby certify fat the foregoing is true and correct Signed	Conversion to Injection
Describe Proposed or Completed Operations (Clearly state all pertiment details, and give pertiment dates, including estimated date of star give subsurface locations and measured and true vertical depths for all markers and zones pertiment to this work.)* 06-16-94: MIRU PU. ND TRE. NU & TEST BOP. POOH W/TBG & PKR. PERF SQZ HO JSPF. SET RTTS PKR @ 7433'. PUMP MARASEAL POLYMER AS FOLLOWS: 240 BBL BBL 50,000 PPM MARASEAL X-LINK GEL & 13 BBL FRESH WTR FLUSH. LET SET OVE PKR. RiH W/2 7/8' PROD TBG. LOAD BACKSDE W/CHEMICALLY INHEITED 2% KCL. 1000 PSI. ND BOP. NU TREE. ROMO. WAIT ON POLYMER SET 7 DAYS. RU SWAB UN FLOWED WELL TO FRAC TANK. TEST PRIOR TO WORK, SI HIGH WATER PRODUCTION. TEST AFTER WORK, 0 BO, 695 MCF, 132 BW DAILY 4. I bereby certify fat the foregoing is true and correct Signed Market the foregoing is true and correct Signed Market of Federal or State office use)	Dispose Water
sive subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 06-16-94: MIRU PU. ND TRE. NU & TEST BOP. POOH W/TBG & PKR. PERF SQZ HO JSPF. SET RTTS PKR @ 7433'. PUMP MARASEAL POLYMER AS FOLLOWS: 240 BBL BBL 50,000 PPM MARASEAL X-LINK GEL & 13 BBL FRESH WTR FLUSH. LET SET OVE PKR. RiH W/2 7/8" PROD TBG. LOAD BACKSIDE W/CHEMICALLY INHIBITED 2% KCL. 1 1000 PSI. ND BOP. NU TREE. RDMO. WAIT ON POLYMER SET 7 DAYS. RU SWAB UN FLOWED WELL TO FRAC TANK. TEST PRIOR TO WORK, SI HIGH WATER PRODUCTION. TEST AFTER WORK, 0 BO, 695 MCF, 132 BW DAILY 4. I bereby certify fat the foregoing is true and correct Signed	(Note: Report setults of multiple completion on W
This space for Federal or State office use)	FRESH H20 PAD, 103 ERNIGHT. POOH W/TBG & TESTED PKR TO
1. I hereby certify that the foregoing is true and correct Signed Theman marker Trice ADV. ENGIN. TECH. (This space for Federal or State office use)	
Signed The ADV. ENGIN. TECH. (This space for Federal or State office use)	
Signed The ADV. ENGIN. TECH. (This space for Federal or State office use)	
Signed The ADV. ENGIN. TECH. (This space for Federal or State office use)	E G
Signed The ADV. ENGIN. TECH. (This space for Federal or State office use)	Ъũ,
Signed The ADV. ENGIN. TECH. (This space for Federal or State office use)	Æ
	Date
Approved by Title	
	Date
Conditions of approval, if any:	
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the Unite or representations as to any matter within its jurisdiction.	od States any false, fictitious or fraudulent stateme