Form 3160-5 (August 1999)

UN **) STATES** DEPARTMENT OF THE INTERIOR

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

5. Lease Serial No.

NM06953

6. If Indian, Allottee or Tribe Name

abandoned well. Use Form	n 3160-3 (APD) for such proposals.	
SUBMIT IN TRIPLICATE - Other instructions on 22224 3016		7. If Unit or CA/Agreement, Name and/or No
Type of Well Oil Well X Gas Well Other Name of Operator Marathon Oil Company	3b. Phono Ry (include area code) 915-682-1620	8. Well Name and No. Federal "C" 35 #1 9. API Well No.
3a. Address P.O. Box 552, Midland, TX 79702 4. Location of Well (Footage, Sec., T., R., M., or Survey L. UL "F", 1650' FNL & 1650' FWL Section 35, T-21-S, R-23-E		30 · 015 · 10403 10. Field and Pool, or Exploratory Area Indian Basin Upper Penn Gas Pool 11. County or Parish, State Eddy NM
12. CHECK APPROPRIATE	BOX(ES) TO INDICATE NATURE OF NOTICE, F	•
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent X Subsequent Report Final Abandonment Notice	Alter Casing Fracture Treat Recl. Casing Repair New Construction Recc. Change Plans Plug and Abandon Tem Convert to Injection Plug Back Water	water Shut-Off well Integrity manation X Other Add perfs porarily Abandon and acidize er Disposal
If the proposal is to deepen directionally or recomp Attach the Bond under which the work will be per following completion of the involved operations. It testing has been completed. Final Abandonment I determined that the final site is ready for final inspection with the second site of the second site of the work commenced 5/6/00. MIRU PU. pump. PU 4-1/2" RBP & RIH to 800 w/4" port plug guns & GR tool. Pw/PPI packers to 7542'. RU Halli CCA sour acid to PPI tool. PUH to 5300 gals. of 15% CCA sour acid. rate - 2.8 BPM. Fished valves & recovering 82 bbls fluid. Release fluid. Released packer & POOH L/	y state all pertinent details, including estimated starting date of a slete horizontally, give subsurface locations and measured and trafformed or provide the Bond No. on file with BLM/BIA. Requif the operation results in a multiple completion or recompletion Notices shall be filed only after all requirements, including recisection.) RU reverse unit & kill well. ND wellhead 19'. Set RBP, load & test to 500 psi. POW 19'. Set RBP, load & test to 500 psi. POW 19'. Powerf from 7486'-7530' w/4 jspf @ 120 degree burton, pickled tbg w/500 gals. 28% HCl at 19' increating perfs from 7530'-7486' in 2' increa	ired subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once amation, have been completed, and the operator has d & NU BOPs. POOH w/tbg & sub OH w/tbg. RU wireline and RIH e phasing. RD wireline & RIH cid. Dropped FCV & spotted 15% ements w/100 gpf for a total of si, Avg press - 2918 psi. Avg. spig. Made 13 swab runs wab runs recovering 42 bbls test to 500 psi. PU & assemble

Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Title

Date

6/2/00

Engineer Technician

Date

I hereby certify that the foregoing is true and correct

Ginny Larke