

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN THE  
(Other instruct.  
reverse side)CATE\*  
on re-Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Las Cruces 063610

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

None

8. FARM OR LEASE NAME

Federal

9. WELL NO.

1

10. FIELD AND POOL OR WILDCAT

PCA Pool Extension

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREASection 22, T-20-S,  
R-30-E, NMFM

12. COUNTY OR PARISH

Eddy

13. STATE

N. Mex.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☐ OTHER ☒

2. NAME OF OPERATOR

Elwyn C. Hale

3. ADDRESS OF OPERATOR

120 Regua Road, Piedmont, California 94611

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface1980' FSL & 1980' FEL, Section 22, T-20-S, R-30-E,  
NMFM, Eddy County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

3250 Gr; 3252 DF (datum)

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.) \*

Abandonment of subject well was accomplished as follows:

1. Shot off 7-inch casing at 1103' and pulled same (7" left cemented in hole  
1103' to 1739').

2. Placed cement plugs via 2-3/8" tubing:

2190' - 1888' : 20 sx 1:1 Class "C" cement and Calseal.

1888' - 1140' : 125 sx Class "C" neat cement.

1140' - 522' : 200 sx Class "C" salt saturated cement.

522 - surface : 180 sx Class "C" neat cement.

3. Set regulation marker in top of well.

4. Levelled pits and cleaned location. Note: Location should be ready for  
inspection by March 27, 1969.Note: Please return approved forms to: L. O. Storm  
901 Michigan, #38  
Hobbs, New Mexico 88240

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Engineer

DATE

March 22, 1969

(This space for Federal or State office use)

APPROVED BY  
CONCURRENCE OF APPROVAL, IF ANY:

TITLE

DATE

RECEIVED

\*See Instructions on Reverse Side

APR 1 1969

D. C. C.  
ARTESIA OFFICE

## Instructions

**General:** This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

**Item 4:** If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

**Item 17:** Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.