

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions
verse side)

DATE
h re

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM-0251099 (A)	
2. NAME OF OPERATOR Amoco Production Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Box 3092, Houston, TX 77253		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit F, 1613' FNL X 2336' FWL, Sec. 12		8. FARM OR LEASE NAME Smith Federal Gas Com	
14. PERMIT NO.		9. WELL NO. #1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3956 RDB		10. FIELD AND POOL, OR WILDCAT Indian Basin Upper Penn	
		11. SEC., T., R., W., OR BLE. AND SURVEY OR AREA 12-22S-23E	
		12. COUNTY OR PARISH Eddy	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETION ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRUSU 7/1/91. P2-3/8" tbg. Unable to get CIBP below 7420. Set CIBP @ 7420. Called Blm. OK to set CIBP @ 7420. R. Bailer X Dump cmt stuck Bailer. Cmt 7364-7319. TAG cmt plug @ 7317. R 4-3/4" OD CSG Cutter.

Cut csg X 5000 ft X POH. Spot cmt plug 5100'-4900'. Isolate csg leak @ 1079'-1110'. Tag cmt X 4774.

Spot 180 sx. cmt plug from 2400'-2200'. Set cmt retainer at 1006' X cmt w/170 sx cmt. Tag cmt X 1900'. TIH X 60' X pmp 15 sx to surf X POH. Cut off wellhead and inst P&A mark. RD X mo Su.

RECEIVED
AUG 9 11 27 AM '91
CARTER
AREA
OFFICE

Surface restoration is completed.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Asst. Admin. Analyst

DATE 8/5/91

(This space for Federal or State office use)

APPROVED BY [Signature]
CONDITIONS OF APPROVAL, IF ANY:

TITLE [Redacted]

8/9/91

1991

*See Instructions on Reverse Side

100

101

102

103

104

105