

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30-015-10619

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
E10171 & K672

7. Lease Name or Unit Agreement Name
CONOCO STATE GAS COM

8. Well No.
1

9. Pool name or Wildcat
INDIAN BASIN (UPPER PENN)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. Name of Operator
KERR-MCGEE OIL & GAS ONSHORE, LLC

3. Address of Operator
P.O. BOX 809004, DALLAS, TX 75380-9004

4. Well Location
Unit Letter F : 1775 Feet From The NORTH Line and 1980 Feet From The WEST Line
Section 2 Township 22S Range 23E NMPM EDDY County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
RKB = 3980'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

ESTIMATED STARTING DATE: 05/15/00

MIRU; POOH W/ RODS & TBG.

RIH W/ 4-1/2" GAUGE RING @ 7300'; RIH W/ CMT. RET. & SET @ 7300'.

SQZ. 100 SXS. CMT. THRU CMT. RET. @ 7300'; PUMP 4 SXS. CMT. ON TOP OF CMT. RET.

CIRC. WELL W/ PXA MUD & PULL UP HOLE W/ TBG.

PUMP A 15 SX CMT. BALANCE PLUG @ 5210'-5360'; POOH W/ TBG.

CUT 4-1/2" CSG. @ 2350'; POOH & LAY DOWN CSG: 2400'-2248'

RIH W/ TBG. & PUMP A 35 SX. CMT. STUB/SHOE PLUG @ 2245'-2350'; WOC & TAG.

PUMP A 35 SX. CMT. SHOE PLUG @ 295'-400'.

PUMP A 20 SX. SURF. PLUG @ 0'-60'; CUT OFF WELLHEAD 3' BGL & SET SURF. MARKER.

1. Perforate 4 1/2" csg @ 5360'. Squeeze 100' cement plug inside + outside 4 1/2" csg. TAG.

2. Perforate 4 1/2" csg @ 3824'. Squeeze 100' cement plug inside + outside 4 1/2" csg. TAG.

* All cement Plugs MIN. 25 SXS.

* Notify N.M. O.C.D. to witness Plugging Operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David A. Eyler TITLE AGENT DATE 04/18/00

TYPE OR PRINT NAME DAVID A. EYLER TELEPHONE NO. 915-687-3033

(This space for State Use)

APPROVED BY mae Stillfield TITLE Field Rep. II DATE 5/8/2000

CONDITIONS OF APPROVAL, IF ANY: