(989)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED Budget Bureau No. 1004-0135 Expires: September 30, 1990

5. Lease Designation and Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS  not use this form for proposals to drill or to deepen or reentry to a different reservoir.		NM 059077
		6. If Indian, Allottee or Tribe Name
		·
Use "APPLICATION FOR PERMIT—" for such	proposals	
		7. If Unit or CA, Agreement Designation
SUBMIT IN TRIPLICATE		
Type of Well		4
Oil To Gas	And the second second second second	8. Well Name and No.
	<u> </u>	<u> </u>
2. Name of Operator	RECEIVED	HOC Fed. #1 9. API Well No.
M W Petroleum Corporation		4
3. Address and Telephone No.	NOV 1 2 1992	30-015-10721
P.O. Box 4628 Houston, Texas 77210	104 2 2 1392	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	Q.C.D.	
1650 FNL 1650 FWL	ARTEGA SECE	11. County or Parish, State
Sect. 13F T-22-S R-23-E	$e^{i\phi}$ . $e^{i\phi}$	
		Eddy, New Mexico
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent X Abandons	ment	Change of Plans
Recomple	•	New Construction
	v.	
()		Non-Routine Fracturing
Casing R	•	Water Shut-Off
Final Abandonment Notice	Casing	Conversion to Injection
Other	(Note: Report results of	multiple completion on Well Completion or
	Recompletion Report as	
3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled,		
give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*,		
70501 1 1		
1) Set $5-1/2$ " cast iron bridge plug at 7650' and cap with 5 sacks cement.		
2) Load hole with mud.		
3) Perforated at 5000'-5001'. Set cement retainer at 4900' unable to pump into		
formation. Spotted 35 sacks cement on top of cement retainer.		
4) Perforated at 2700'-2701'. Set cement retainer at 2600' unable to pump into		
formation. Spotted 40 sacks cement on top of cement retainer.		
5) Spotted 10 sacks cement from 100' to surface and set up P&A marker.		
t = -t	• 5	
·	•	0 4-0 4
		Post ID-2 11-13-92
		11-13-40
المراجع المراج المراجع المراجع المراج	· ·	PYA
	a tra	
And the second of the second o		1
	Burney Commencer	
0	•	
4. I hereby certify that the foregoing is true and correct/		
Signed Hayman Madanak Title Supe	micon.	Date 10-12-92
(This areas for Endered or State office use)		
(This space for Federal or State office use)		100
Approved by Title		Date
Conditions of approval, if any:		
•		