

March 2, 1973

Page Two

3. The mud properties at T. D. on the original well were as follows:

8.5 weight
75 viscosity
2.4 water loss
1/32 filter cake
9.0 pH
18% oil

4. Approximately 220 bbls of fluid were lost at 7520'. Full circulation had been regained at T.D.

ESTIMATED COSTS: (\$3,000.00 to \$5,000.00)

1. The above estimated costs do not include severe loss circulation or extreme pressure.

SERVICE ENGINEER:

Lee Roberts, Hobbs, N.M., Ph: 505 393 8703, Mobile: 505 393 7241
Hobbs Warehouse, Ph: 505 393 5421

I trust the foregoing information will be of benefit and if we may be of any further service, please let us know.

Yours very truly,

MUSTANG MUD, INC.

A. J. Cain

pf