

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-1189-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME Big Eddy Unit
2. NAME OF OPERATOR Pan American Petroleum Corp.	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR Box 68, Hobbs, New Mexico 88240	9. WELL NO. 9
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FNL x 660' FEL, Sec. 19 (UNIT H, SE 1/4 NE 1/4)	10. FIELD AND POOL, OR WILDCAT UNDESIGNATED
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, OR, etc.) 3533' R.D.B.
12. COUNTY OR PARISH Eddy	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

FULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Drilled to a depth of 13,128' without encountering commercial quantities of oil or gas. Propose to plug and abandon as follows:

Cement Plugs

150 sx. 13,128 - 12,500

125 sx. 11,500 - 11,750

50 sx. 10,600 - 10,500

50 sx. 9,100 - 9,000

50 sx. 7,100 - 7,000

50 sx. 5,600 - 5,500

Cement plugs

50 sx. In and out of 8 3/8" shoe @ 3925'

300 sx. 2100 - 850 (Salt Section)

10 sx. Surface w/ P.A. marker

Final cleanup will be made and ground is to contour.

(16" CSA 760' @ mt circ)

(11 3/4" CSA 2257)

(8 3/8" CSA 3925 w/ 1050 sx - 2 stage)

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Supt

DATE

6-24-66

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

JUN 27 1966

RUDOLPH C. BAUER, JR.
ACTING DISTRICT ENGINEER

NOTIFY USGS IN SUFFICIENT TIME TO

WITNESS CEMENTING THE

*See Instructions on Reverse Side

ON 4 USGS ART
1-NSW
1-SUSP
1-RRV
1-STATE LAND
1-PERRY R. BASS