UI ED STATES N. M. O. C. C. COPY SUBMIT IN TRIL ATE* Other instructions on reverse side) OTHER INTERIOR (Other instructions)

Form approved. Budget Bureau No. 42-R1424.

5.	LEASE	DESIGNATION			AND	SERIAL
		ΝT	3,5	024	77	

İ	5.	LEASE	DE	SIGN	ATION	AND	SERIAL	NO
l			ΝT	3.5	026	מח		

		GEOLOGICAL SUI	RVEY	LAHA	N.M. 036	77	
	Allowed new this form for propo	ICES AND REP	en or plug back t	to a different reservoir.	6. IF INDIAN, ALLOTTEE	OR TRIBE NAME	
1.					7. UNIT AGREEMENT NAM	1 E	
	WELL X WELL OTHER				Harvey E. Y	ates	
	NAME OF OPERATOR		8. FARM OR LEASE NAME				
	Harvey E. Yates	Stebbins De	ep Federal				
3.	ADDRESS OF OPERATOR				9. WELL NO.	·*	
		Antesia New	Marian		2 - Y		
4.	305 Carper Bldg.	dearly and in accordance	e with any State	e requirements.*	10. FIELD AND POOL, OR WILDCAT		
	See also space 17 below.) At surface	·		-	Wildcat		
	SW/4 SW/4 NE/4 30	0-20-29			11. SEC., T., R., M., OR BLK. AND		
	2310 fr North and	*			SURVEY OR AREA		
	2010 11 1101 011 0110	22/) 11 Labo			30-20-29		
		15. ELEVATIONS (Show	whathan are pr	GU oto)	12. COUNTY OR PARISH	13 STATE	
14.	PERMIT NO.	15. ELEVATIONS (SHOW	whether br, kt,	(iii, etc.)		N.M.	
					Eddy	14 • 14 •	
16.	Check A	ppropriate Box To I	ndicate Natu	re of Notice, Report, or C	Other Data	i .	
	NOTICE OF INTE	QUENT REPORT OF:					
	TEST WATER SHUT-OFF	PULL OR ALTER CASING		WATER SHUT-OFF	REPAIRING W	ELL	
	; 	MULTIPLE COMPLETE		FRACTURE TREATMENT	ALTERING CA		
	FRACTURE TREAT		X	SHOOTING OR ACIDIZING	ABANDONMEN		
	SHOOT OR ACIDIZE	ABANDON*	**		ABANDONNEL	-	
	(Other)	CHANGE PLANS		(Other) (Note: Report results	of multiple completion eletion Report and Log for	on Well	
17	DESCRIBE PROPOSED OR COMPLETED OF	ERATIONS (Clearly state	all pertinent de				
- • •	proposed work. If well is directinent to this work.) *	onally drilled, give subs	surface locations	and measured and true vertical	al depths for all markers	and zones perti-	
	nelle to this work.						
	We intend to plug a	and abandon th	is well in	n the following mar	ner.		
						1 · · · · · · · · · · · · · · · · · · ·	
	Run drill pipe to	3190. Place a	100 cmt p	olug back to 3090.	Place a 100 cm	t "•	
	plug from 1015 to	1115. Then a	100 cmt p1	lug from 650 to 750). Then a 20 cm	t	
	plug at surface wi	th regulation (drv hole m	marker.			
	1240 at partage #1						

RECEIVED

JUL 19 1966 SURVEY.

J. S. GEOLOGICAL NEW WEXICO.

J. S. GEOLOGICAL NEW WEXICO.

18. I hereby certify that the foregoing is true and cor	rect			
SIGNED	TITLE	Bookkeeper	DATE _	July 19, 1966
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	м	*	DATE	JOE 2 1 1050