

13 7/8" - 700 - Circ. 9 5/8" - 3035 - TOC 1160

Ag. fs 1538-1936 . 300 SX. + 150 SX.

reg. fs 1538-1936 . 300 SX -

7" - 3985 - 425 SX. TOC - 3020

P 3680-85 Ag. fs 3180-85 w/ 150 SX.

set 4 1/2" - 11860 - 1400 SX. TOC - 6070

f 11706-716 water

f 11736-746 - water - Plug to P & A Drill mtn. 3/12

13 7/8" - 700 9 5/8" - 3035 - BS - 5348

7" - 3985 - 425 TOC - 3020 -

4 1/2" - 11860 - 1400 TOC - 6070 fs 11706-716 736-746

2-19-79 8:10 AM. Don Lane.

CIBP @ 11650 w/ 35' cement

Cut & pull 4 1/2" approx. 6070 on true point

spot 100' plug at stub + lose one @ 535400

100' plug. 3950-4050

Cut & pull 7" from 3000' 100 plug at stub

surface plug w/ marker.

