

NEW MEXICO OIL FIELD REPORT
DRAWER 100
ARTESIA, NEW MEXICO

FIELD REPORT FOR CEMENTING OF WELLS

Operator <u>J. M. Huber Corp</u>		Lease <u>Humble State</u>		Well # <u>1</u>	
Location of Well	Unit <u>M</u>	Section <u>23</u>	Township <u>21</u>	Range <u>27</u>	County <u>Edgely</u>
Drilling Contractor	<u>66058w</u> <u>Nobel & Will</u>		Type of Equipment <u>Rotary</u>		
<u>APPROVED CASING PROGRAM</u>					
Size of Hole	Size of Casing	Weight Per Foot	New or Used	Depth	Sacks Cement
<u>17 1/2</u>	<u>13 3/8</u>	<u>48.54.5</u>		<u>700</u>	<u>Circ</u>
<u>12 1/4</u>	<u>9 5/8</u>	<u>40</u>		<u>3200</u>	<u>800</u>
<u>8 3/4</u>	<u>5 1/2 or 17"</u>	<u>17.826</u>		<u>10800</u>	<u>8000</u> <u>P.</u>
Casing Data:					
Surface <u>98</u> joints of <u>9 5/8</u> inch <u>40</u> # Grade <u>J 40</u>					
(Approved) (Rejected)					
Inspected by <u>H. L. L.</u> date <u>2-3-67</u>					
Cementing Program					
Size of hole <u>12 1/4</u> Size of Casing <u>9 5/8</u> Sacks cement required					
Type of Shoe used <u>G. 1/2</u> Float collar used <u>✓</u> Btm 3 jts welded <u>✓</u>					
TD of hole <u>3035</u> Set Fast of <u>1 1/2</u> inch <u>40</u> # Grade <u>J 40</u>					
New-used csg. @ <u>3034</u> with <u>200</u> sacks neat cement around shoe <u>2% CaCl</u>					
+ <u>140</u> sack <u>4 1/2 gal 10 1/2 # gill/sack additives</u> <u>2% CaCl</u>					
Plug down @ <u>11:20</u> (AM) (PM) Date <u>2-4-67</u>					
Cement circulated <u>No</u> No. of Sacks					
Cemented by <u>H. L. L.</u> Witnessed by <u>R. L. L.</u>					
Temp. Survey ran @ <u>3:30</u> (AM) (PM) Date <u>2-5-67</u> Top cement @ <u>1169</u>					
Casing test @ (AM) (PM) Date					
Method Used Witnessed by					
Checked for shut off @ (AM) (PM) Date					
Method used Witnessed by					
Remarks:					

Dr Tool 11:20. Sed stage 1905x c 4 1/2 gal 12 1/4 gill/sack 2% CaCl
+ 505x c 1/4 # floccle/sack 2% CaCl

Baskets 1715 & 1700

Cement 1700 302.5, 2990 1700, 1669