Form 9-331 (May 1963)						
		NITED STATES	SUBMIT IN (Other Instr	PLICATE DB on re-	Form approved. Budget Bureau 5. LEASE DESIGNATION AN	
		GEOLOGICAL SURVEY	A A	mit Al	LC-070286	
	<u>.</u>	· · · · · · · · · · · · · · · · · · ·		py 1-1	6. IF INDIAN, ALLOTTED O	R TRIBE NAME
		TICES AND REPORTS			•	
(1)0 1101	Use this form for prop Use "APPLIC	osals to drill or to deepen or plug CATION FOR PERMIT—" for such	proposals.)	ervoir.	·	·
our 🖵		·····			7. UNIT AGREEMENT NAME	,
WELL	WELL OTHER					
NAME OF OPE					8. FARM OR LEASE NAME	33
Pennzoil Company 3. Address of Operator					Hudson-Feder	al
		avinge Ruilding	Midland Mar		9. WELL NO. 2	1
1007 Midland Savings Building, Midland, Texas 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*					10. FIELD AND POOL, OR WILDCAT	
See also space 17 below.) At surface					Undesignated Penn.	
100					11. SEC., T., B., M., OR BLK	
190	U' FSL, 105	0' FWL, Section 3	33, T-20-S, I		SURVEY OR AREA	
					Sec 33, T-20-	S,R-30-
4. PERMIT NO.		15. ELEVATIONS (Show whether	DF, RT, GR, etc.)		12. COUNTY OR PARISH 1	3. STATE
		3381.4 GL			Eddy	N. Mex
3.	Check A	Appropriate Box To Indicate	Nature of Notice	Report or Of	ther Data	
	NOTICE OF INTE		1		INT REPORT OF:	. 1
				- -		
TEST WATER		PULL OR ALTER CASING	WATER SHUT-O		REPAIRING WE	
FRACTURE TH		ABANDON*	FRACTURE TREASED		ABANDONMENT ⁴	
REPAIR WEL		CHANGE PLANS	(Other) Cas			x
(Other)	LJ		(Note:]	Report results o	of multiple completion on tion Report and Log form.	
7. DESCRIBE PRO	POSED OR COMPLETED OF	PERATIONS (Clearly state all pertin	ent details, and give pe	rtinent dates, i	including estimated date of	of starting an
nent to this	work, if well is direct s work.) *	tionally drilled, give subsurface lo	cations and measured ar	ia true vertical	depins for all markers a	nu zones pert
5-67 -						· ·
			Don 104 -+-	~ ~ £ 0 5		- - - -
5 67			2		/8" OD, 32# 3	
	casing to ϵ	4024' with float	collar at 39	992' and	l DV packer at	t 1936'
	casing to and two cer	4024' with float ment baskets at l	collar at 39 .931 and 1899	992' and 9'. Cem	DV packer at mented first s	t 1936' stage
	casing to and two cen with 450 S:	4024' with float ment baskets at l x Class C w/4% ge	collar at 39 .931 and 1899 e1, and ½# f1	992' and 9'. Cem locele p	DV packer at mented first s mer sack plus	t 1936' stage 150 Sx
	casing to and two cen with 450 S Class C w/	4024' with float ment baskets at 1 x Class C w/4% ge 2% HA-5 and ¼# fl	collar at 39 931 and 1899 e1, and $\frac{1}{4}$ # f ocele per sa	992' and 9'. Cem locele p ack. Pl	DV packer at mented first s per sack plus ug down at 10	t 1936' stage 150 Sx 0:45
	casing to and two cen with 450 S Class C w/ P.M. Open	4024' with float ment baskets at l x Class C w/4% ge 2% HA-5 and 칰# fl ed DV tool and ce	collar at 39 .931 and 1899 e1, and ¼# f1 .ocele per sa emented secon	992' and 9'. Cem Locele p ack. Pl nd stage	DV packer at mented first s per sack plus ug down at 10 with 450 Sx	t 1936' stage 150 Sx D:45 Class
	casing to and two cen with 450 S: Class C w/ P.M. Open w/4% gel, a	4024' with float ment baskets at 1 x Class C w/4% ge 2% HA-5 and ½# fl ed DV tool and ce and ¼# flocele pe	collar at 39 931 and 1899 el, and ¼# f ocele per sa emented secon er sack plus	992' and 9'. Cem locele p ack. Pl nd stage 150 Sx	DV packer at mented first s per sack plus ug down at 10 with 450 Sx Class C w/4#	t 1936' stage 150 Sx 0:45 Class flocel
	casing to and two cen with 450 S Class C w/ P.M. Open w/4% gel, a per sack.	4024' with float ment baskets at 1 x Class C w/4% ge 2% HA-5 and ½# fl ed DV tool and ce and ¼# flocele pe Closed DV tool w	collar at 39 931 and 1899 e1, and $\frac{1}{4}$ # f ocele per sa emented second er sack plus with 2000# pr	992' and 9'. Cem Locele p ack. Pl nd stage 150 Sx cessure.	DV packer at mented first s oer sack plus ug down at 10 with 450 Sx Class C w/4# Cement did	t 1936' stage 150 Sx 0:45 Class flocel not
	casing to and two cer with 450 S Class C w/ P.M. Open w/4% gel, a per sack. circulate.	4024' with float ment baskets at 1 x Class C w/4% ge 2% HA-5 and ½# fl ed DV tool and ce and ½# flocele pe Closed DV tool w Ran temperature	collar at 39 931 and 1899 1, and ¼# f ocele per sa emented secon er sack plus with 2000# pu survey. To	992' and 9'. Cem Locele p ack. Pl nd stage 150 Sx cessure. op cemen	DV packer at hented first s ber sack plus ug down at 10 with 450 Sx Class C w/4 Cement did t at 1750°.	t 1936' stage 150 Sx 0:45 Class flocel not Ran 2"
	casing to and two cer with 450 S: Class C w/ P.M. Open w/4% gel, a per sack. circulate. pipe to 17	4024' with float ment baskets at 1 x Class C w/4% ge 2% HA-5 and ¼# fl ed DV tool and ce and ¼# flocele pe Closed DV tool w Ran temperature 24' outside 8-5/8	collar at 39 931 and 1899 e1, and ½# f1 ocele per sa emented secon er sack plus with 2000# pu survey. To 3. Cemented	992' and 9'. Cem locele p ack. Pl nd stage 150 Sx cessure. op cemen with 34	DV packer at hented first s ber sack plus ug down at lo with 450 Sx Class C w/4# Cement did t at 1750°.	t 1936' stage 150 Sx 0:45 Class flocel not Ran ½" w/¼#
	casing to and two cer with 450 S: Class C w/ P.M. Opene w/4% gel, a per sack. circulate. pipe to 17 flocele per	4024' with float ment baskets at 1 x Class C w/4% ge 2% HA-5 and ½# fl ed DV tool and ce and ¼# flocele pe Closed DV tool w Ran temperature 24' outside 8-5/8 r sack. Circulat	collar at 39 931 and 1899 e1, and $\frac{1}{4}$ # f ocele per sa emented secon er sack plus with 2000# pr survey. To b. Cemented ced estimated	992' and 9'. Cem locele p ack. Pl nd stage 150 Sx ressure. op cemen with 34 1 25 Sx.	DV packer at hented first s oer sack plus ug down at 10 with 450 Sx Class C w/4 Cement did t at 1750 ¹ . O Sx Class C Job complet	t 1936' stage 150 Sx 0:45 Class flocel not Ran ½" w/½# te at
	casing to and two cen with 450 S Class C w/2 P.M. Open w/4% gel, a per sack. circulate. pipe to 172 flocele per 9:45 p.m.	4024' with float ment baskets at 1 x Class C w/4% ge 2% HA-5 and ½# fl ed DV tool and ce and ¼# flocele pe Closed DV tool w Ran temperature 24' outside 8-5/8 r sack. Circulat After 24 hrs W.C	collar at 39 931 and 1899 e1, and ½# f ocele per sa emented secon er sack plus with 2000# pr survey. To b. Cemented ed estimated 0.C. tested of	992' and 9'. Cem locele p ack. Pl nd stage 150 Sx cessure. op cemen with 34 d 25 Sx. casing w	DV packer at hented first s oer sack plus ug down at 10 with 450 Sx Class C w/4 Cement did t at 1750 ¹ . O Sx Class C Job complet	t 1936' stage 150 Sx 0:45 Class flocel not Ran ½" w/½# te at
	casing to and two cen with 450 S Class C w/2 P.M. Open w/4% gel, a per sack. circulate. pipe to 172 flocele per 9:45 p.m.	4024' with float ment baskets at 1 x Class C w/4% ge 2% HA-5 and ½# fl ed DV tool and ce and ¼# flocele pe Closed DV tool w Ran temperature 24' outside 8-5/8 r sack. Circulat	collar at 39 931 and 1899 e1, and ½# f ocele per sa emented secon er sack plus with 2000# pr survey. To b. Cemented ed estimated 0.C. tested of	992' and 9'. Cem locele p ack. Pl nd stage 150 Sx cessure. op cemen with 34 d 25 Sx. casing w	DV packer at hented first s oer sack plus ug down at 10 with 450 Sx Class C w/4 Cement did t at 1750 ¹ . O Sx Class C Job complet	t 1936' stage 150 Sx 0:45 Class flocel not Ran ½" w/½# te at
	casing to and two cen with 450 S Class C w/2 P.M. Open w/4% gel, a per sack. circulate. pipe to 172 flocele per 9:45 p.m.	4024' with float ment baskets at 1 x Class C w/4% ge 2% HA-5 and ½# fl ed DV tool and ce and ½# flocele pe Closed DV tool w Ran temperature 24' outside 8-5/8 r sack. Circulat After 24 hrs W.C drilling DV tool.	collar at 39 931 and 1899 e1, and ½# f ocele per sa emented secon er sack plus with 2000# pr survey. To b. Cemented ed estimated 0.C. tested of	992' and 9'. Cem locele p ack. Pl nd stage 150 Sx cessure. op cemen with 34 d 25 Sx. casing w	DV packer at hented first s oer sack plus ug down at 10 with 450 Sx Class C w/4 Cement did t at 1750 ¹ . O Sx Class C Job complet	t 1936' stage 150 Sx 0:45 Class flocel not Ran ½" w/½# te at
	casing to and two cen with 450 S Class C w/2 P.M. Open w/4% gel, a per sack. circulate. pipe to 172 flocele per 9:45 p.m.	4024' with float ment baskets at 1 x Class C w/4% ge 2% HA-5 and ½# fl ed DV tool and ce and ½# flocele pe Closed DV tool w Ran temperature 24' outside 8-5/8 r sack. Circulat After 24 hrs W.C drilling DV tool.	collar at 39 931 and 1899 e1, and $\frac{1}{4}$ # f ocele per sa emented second er sack plus with 2000# pr survey. To b. Cemented ed estimated o.C. tested of Tested o.P	992' and 9'. Cem locele p ack. Pl nd stage 150 Sx cessure. op cemen with 34 d 25 Sx. casing w	DV packer at hented first s oer sack plus ug down at 10 with 450 Sx Class C w/4 Cement did t at 1750 ¹ . O Sx Class C Job complet	t 1936' stage 150 Sx 0:45 Class flocel not Ran ½" w/½# te at
	casing to and two cen with 450 S Class C w/2 P.M. Open w/4% gel, a per sack. circulate. pipe to 172 flocele per 9:45 p.m.	4024' with float ment baskets at 1 x Class C w/4% ge 2% HA-5 and ½# fl ed DV tool and ce and ½# flocele pe Closed DV tool w Ran temperature 24' outside 8-5/8 r sack. Circulat After 24 hrs W.C drilling DV tool.	collar at 39 931 and 1899 e1, and $\frac{1}{4}$ # f ocele per sa emented second er sack plus with 2000# pr survey. To b. Cemented ed estimated o.C. tested of Tested o.P	992' and 9'. Cem locele p ack. Pl nd stage 150 Sx cessure. op cemen with 34 d 25 Sx. casing w	DV packer at hented first s oer sack plus ug down at 10 with 450 Sx Class C w/4 Cement did t at 1750 ¹ . O Sx Class C Job complet	t 1936' stage 150 Sx 0:45 Class flocel not Ran ½" w/½# te at
	casing to and two cen with 450 S Class C w/2 P.M. Open w/4% gel, a per sack. circulate. pipe to 172 flocele per 9:45 p.m.	4024' with float ment baskets at 1 x Class C w/4% ge 2% HA-5 and ½# fl ed DV tool and ce and ½# flocele pe Closed DV tool w Ran temperature 24' outside 8-5/8 r sack. Circulat After 24 hrs W.C drilling DV tool.	collar at 39 931 and 1899 e1, and $\frac{1}{4}$ # f ocele per sa emented second er sack plus with 2000# pr survey. To b. Cemented ed estimated o.C. tested of Tested o.P	992' and 9'. Cem locele p ack. Pl nd stage 150 Sx cessure. op cemen with 34 1 25 Sx. casing w c.	DV packer at hented first s oer sack plus ug down at 10 with 450 Sx Class C w/4 Cement did at at 1750'. 0 Sx Class C Job complet 7/3000# prior	t 1936' stage 150 Sx 0:45 Class flocel not Ran ½" w/½# te at
	casing to and two cen with 450 S Class C w/2 P.M. Open w/4% gel, a per sack. circulate. pipe to 172 flocele per 9:45 p.m.	4024' with float ment baskets at 1 x Class C w/4% ge 2% HA-5 and ½# fl ed DV tool and ce and ½# flocele pe Closed DV tool w Ran temperature 24' outside 8-5/8 r sack. Circulat After 24 hrs W.C drilling DV tool.	collar at 39 931 and 1899 e1, and $\frac{1}{4}$ # f ocele per sa emented second er sack plus with 2000# pr survey. To b. Cemented ed estimated o.C. tested of Tested o.P	992' and 9'. Cem locele p ack. Pl nd stage 150 Sx cessure. op cemen with 34 1 25 Sx. casing w c.	DV packer at hented first s oer sack plus ug down at 10 with 450 Sx Class C w/4 Cement did at at 1750'. 0 Sx Class C Job complet 7/3000# prior	t 1936' stage 150 Sx 0:45 Class flocel not Ran ½" w/½# te at
	casing to and two cer with 450 S: Class C w/ P.M. Open w/4% gel, a per sack. circulate. pipe to 17 flocele per 9:45 p.m. and after o	4024' with float ment baskets at 1 x Class C w/4% ge 2% HA-5 and ¼# fl ed DV tool and ce and ¼# flocele pe Closed DV tool w Ran temperature 24' outside 8-5/8 r sack. Circulat After 24 hrs W.C drilling DV tool.	collar at 39 931 and 1899 e1, and $\frac{1}{4}$ # f ocele per sa emented second er sack plus with 2000# pr survey. To b. Cemented ed estimated o.C. tested of Tested o.P	992' and 9'. Cem locele p ack. Pl nd stage 150 Sx cessure. op cemen with 34 1 25 Sx. casing w c.	DV packer at hented first s oer sack plus ug down at 10 with 450 Sx Class C w/4 Cement did at at 1750'. 0 Sx Class C Job complet 7/3000# prior	t 1936' stage 150 Sx 0:45 Class flocel not Ran ½" w/½# te at
	casing to and two cer with 450 S: Class C w/ P.M. Open w/4% gel, a per sack. circulate. pipe to 17 flocele per 9:45 p.m. and after o	4024' with float ment baskets at 1 x Class C w/4% ge 2% HA-5 and ¼# fl ed DV tool and ce and ¼# flocele pe Closed DV tool w Ran temperature 24' outside 8-5/8 r sack. Circulat After 24 hrs W.C drilling DV tool.	collar at 39 931 and 1899 e1, and ¼# f1 ocele per sa emented secon er sack plus with 2000# pr survey. To b. Cemented ced estimated o.C. tested o. Tested o. E C E I V E	992' and 9'. Cem locele p ack. Pl nd stage 150 Sx cessure. op cemen with 34 1 25 Sx. casing w c.	DV packer at hented first s oer sack plus ug down at 10 with 450 Sx Class C w/4 Cement did at at 1750'. 0 Sx Class C Job complet 7/3000# prior	t 1936' stage 150 Sx 0:45 Class flocel not Ran 'z" w/'z# te at to
	casing to and two cer with 450 S: Class C w/ P.M. Open w/4% gel, a per sack. circulate. pipe to 17 flocele per 9:45 p.m. and after o	4024' with float ment baskets at 1 x Class C w/4% ge 2% HA-5 and ¼# fl ed DV tool and ce and ¼# flocele pe Closed DV tool w Ran temperature 24' outside 8-5/8 r sack. Circulat After 24 hrs W.C drilling DV tool.	collar at 39 931 and 1899 e1, and $\frac{1}{4}$ # f ocele per sa emented second er sack plus with 2000# pr survey. To b. Cemented ed estimated o.C. tested of Tested o.P	992' and 9'. Cem locele p ack. Pl nd stage 150 Sx cessure. op cemen with 34 1 25 Sx. casing w c.	DV packer at hented first s oer sack plus ug down at 10 with 450 Sx Class C w/4 Cement did at at 1750'. 0 Sx Class C Job complet 7/3000# prior	t 1936' stage 150 Sx 0:45 Class flocel not Ran ½" w/½# te at
8. I hereby cert SIGNED	casing to and two cer with 450 S: Class C w/2 P.M. Open w/4% gel, a per sack. circulate. pipe to 17 flocele pe: 9:45 p.m. and after tify that the foregoing	4024' with float ment baskets at 1 x Class C w/4% ge 2% HA-5 and ¼# fl ed DV tool and ce and ¼# flocele pe Closed DV tool w Ran temperature 24' outside 8-5/8 r sack. Circulat After 24 hrs W.C drilling DV tool.	collar at 39 931 and 1899 e1, and ¼# f1 ocele per sa emented secon er sack plus with 2000# pr survey. To b. Cemented ced estimated o.C. tested o. Tested o. E C E I V E	992' and 9'. Cem locele p ack. Pl nd stage 150 Sx cessure. op cemen with 34 1 25 Sx. casing w c.	DV packer at hented first s ber sack plus ug down at 10 with 450 Sx Class C w/4 Cement did t at 1750'. 0 Sx Class C Job complet 7/3000# prior	t 1936' stage 150 Sx 0:45 Class flocel not Ran 'z" w/'z# te at to
18. I hereby cert SIGNED (This space	casing to and two cer with 450 S: Class C w/2 P.M. Open w/4% gel, a per sack. circulate. pipe to 17 flocele pe: 9:45 p.m. and after tify that the foregoing	4024' with float ment baskets at 1 x Class C w/4% ge 2% HA-5 and ¼# fl ed DV tool and ce and ¼# flocele pe Closed DV tool w Ran temperature 24' outside 8-5/8 r sack. Circulat After 24 hrs W.C drilling DV tool.	collar at 39 931 and 1899 e1, and ¼# f1 ocele per sa emented secon er sack plus with 2000# pr survey. To b. Cemented ced estimated o.C. tested o. Tested o. E C E I V E	992' and 9'. Cem locele p ack. Pl nd stage 150 Sx cessure. op cemen with 34 1 25 Sx. casing w c.	DV packer at hented first s oer sack plus ug down at 10 with 450 Sx Class C w/4 Cement did at at 1750'. 0 Sx Class C Job complet 7/3000# prior	t 1936' stage 150 Sx 0:45 Class flocel not Ran 'z" w/'z# te at to
18. I hereby cert SIGNED (This space	casing to and two cer with 450 S: Class C w/2 P.M. Open w/4% gel, a per sack. circulate. pipe to 17 flocele pe: 9:45 p.m. and after tify that the foregoing	4024' with float ment baskets at 1 x Class C w/4% ge 2% HA-5 and ¼# fl ed DV tool and ce and ¼# flocele pe Closed DV tool w Ran temperature 24' outside 8-5/8 r sack. Circulat After 24 hrs W.C drilling DV tool.	collar at 39 931 and 1899 e1, and ¼# f1 ocele per sa emented secon er sack plus with 2000# pr survey. To b. Cemented ced estimated o.C. tested o. Tested o. E C E I V E	992' and 9'. Cem locele p ack. Pl nd stage 150 Sx cessure. op cemen with 34 1 25 Sx. casing w c.	DV packer at hented first s oer sack plus ug down at 10 with 450 Sx Class C w/4 Cement did at at 1750'. 0 Sx Class C Job complet 7/3000# prior	t 1936' stage 150 Sx 0:45 Class flocel not Ran 'z" w/'z# te at to
18. I hereby cert SIGNED (This space	casing to and two cer with 450 S: Class C w/2 P.M. Open w/4% gel, a per sack. circulate. pipe to 17 flocele pe: 9:45 p.m. and after tify that the foregoing	4024' with float ment baskets at 1 x Class C w/4% ge 2% HA-5 and ¼# fl ed DV tool and ce and ¼# flocele pe Closed DV tool w Ran temperature 24' outside 8-5/8 r sack. Circulat After 24 hrs W.C drilling DV tool.	collar at 39 931 and 1899 e1, and ¼# f1 ocele per sa emented secon er sack plus with 2000# pr survey. To b. Cemented ced estimated o.C. tested o. Tested o. E C E I V E	992' and 9'. Cem locele p ack. Pl nd stage 150 Sx cessure. op cemen with 34 1 25 Sx. casing w c.	DV packer at hented first s oer sack plus ug down at 10 with 450 Sx Class C w/4 Cement did at at 1750'. 0 Sx Class C Job complet 7/3000# prior	t 1936' stage 150 Sx 0:45 Class flocel not Ran 'z" w/'z# te at to
18. I hereby cert SIGNED (This space APD TTON APR	casing to and two cen with 450 S: Class C w/1 P.M. Open w/4% gel, a per sack. circulate. pipe to 17 flocele pe: 9:45 p.m. and after tify that the foregoing	4024' with float ment baskets at 1 x Class C w/4% ge 2% HA-5 and ¼# fl ed DV tool and ce and ¼# flocele pe Closed DV tool w Ran temperature 24' outside 8-5/8 r sack. Circulat After 24 hrs W.C drilling DV tool.	collar at 39 931 and 1899 el, and ¼# fi- ocele per sa emented second er sack plus with 2000# pro- survey. To be survey. To be contended of estimated of tested of tested of tested of tested of tested of tested of tested of tested of tested of tested of tested of tested of tested of tested of tested of tested of tested of test	992' and 9'. Cem locele p ack. Pl nd stage 150 Sx cessure. op cemen with 34 1 25 Sx. casing w c.	DV packer at hented first s oer sack plus ug down at 10 with 450 Sx Class C w/4 Cement did at at 1750'. 0 Sx Class C Job complet 7/3000# prior	t 1936' stage 150 Sx 0:45 Class flocel not Ran 'z" w/'z# te at to
18. I hereby cert SIGNED (This space APD TTON APR	casing to and two cer with 450 S: Class C w/ P.M. Open w/4% gel, a per sack. circulate. pipe to 17 flocele pe: 9:45 p.m. and after a	4024' with float ment baskets at 1 x Class C w/4% ge 2% HA-5 and ¼# fl ed DV tool and ce and ¼# flocele pe Closed DV tool w Ran temperature 24' outside 8-5/8 r sack. Circulat After 24 hrs W.C drilling DV tool.	collar at 39 931 and 1899 e1, and ¼# f1 ocele per sa emented secon er sack plus with 2000# pr survey. To b. Cemented ced estimated o.C. tested o. Tested o. E C E I V E	992' and 9'. Cem locele p ack. Pl nd stage 150 Sx cessure. op cemen with 34 1 25 Sx. casing w c.	DV packer at hented first s oer sack plus ug down at 10 with 450 Sx Class C w/4 Cement did at at 1750'. 0 Sx Class C Job complet 7/3000# prior	t 1936' stage 150 Sx 0:45 Class flocel not Ran 'z" w/'z# te at to

•