NO. OF COPIES RECEIVED	3		
DISTRIBUTION			
SANTA FE			_
FILE	1	-	
U.S.G.S.			
LAND OFFICE			
OPERATOR	\top	1	

DISTRIBUTION				Supersedes Old
SANTA FE			NEW MEXICO OIL CONSERVATION COMMISSION -	C-102 and C-103
FILE	1	٢	NEW MEXICO OIL CONSERVATION COMMISSION E D	Effective 1-1-65
U.S.G.S.			K 2 -	5a. Indicate Type of Lease
LAND OFFICE			OOT 0 1 1074	
OPERATOR			OCT 2 1 1974	5. State Oil & Gas Lease No.
				_
	SLII	NDR	Y NOTICES AND REPORTS ON WELLS . C.	KYYYYY K-851
(DO NOT USE THIS FO	APPL	R PRO	POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DICETES A BENTON ON FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS	
l. OIL GAS				7. Unit Agreement Name
WELL WEL	<u> </u>	X	OTHER-	
2. Name of Operator				8. Farm or Lease Name
2 11)	She	enai	ndoah Oil Corporation	Chala ar
3. Address of Operator				9. Well No.
	150	00 (Commerce Building, Fort North, Texas 76102	μ2
4. Location of Well		153		10. Field and Pool, or Wildcat
UNIT LETTER G			1655 FEET FROM THE N LINE AND 1650 FEET FROM	Mol/d 11 am M
				MCMILLER MORROW CAS
THE	INE, S	ECTIO	N 24 TOWNSHIP 20 E RANGE 26 E NMPM.	
in i		•		
		$^{\prime\prime\prime\prime}$	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
İMININI (1971)	7777.	7//	3.308 OF	Eddy
	Che	ck A	appropriate Box To Indicate Nature of Notice, Report or Otl	ner Data
NOTIC	CE O	FIN		REPORT OF:
_	٦			
PERFORM REMEDIAL WORK	1		PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	┥		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	J		CHANGE PLANS CASING TEST AND CEMENT JQB	
OTHER			OTHER	
OTHER				
17. Describe Proposed or Con	mplete	d Ope	erations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
				is system only any proposed
1) Estimate	rec	ove:	ring 6900' - $5\frac{1}{2}$ csg.	
2) Estimate	***	n+4.	ng work 11-1-74	
-7 23-0111106	D VEL	COLI	ig work 11-1-74	
3) Plugs as	Pol 1		·	
· · · · · · · · · · · · · · · · · · ·			• •	
60 ak	Cen	een t	plug from 10,399 - 10,149	
60 sk	CEL	een (plug from 6950 - 6800	
60 ak		eeu (plug from 5250 - 5350	
do Santa	Cen	ent	plug from 2650 - 2750	
/ (- 8K	cen	ent	plug from 10' to surface	
4) Weld on P		_ 4		
T/ WELU ON P	œ A	st	eel plate. Install dry hole marker and clean u	r location
werr All	Dе	aba	ndoned due to depleted gas zone.	T ACOUTOTT 6
5) 150' cement plug where csg is cut off 50' below 100' above.				
			•	
18. I hereby certify that the in	ıformat	ion a	bove is true and complete to the best of my knowledge and belief.	
,,		a	and the complete to the best of my knowledge and belief.	

DATE 10-16-74 OIL AND GAS INSPECTOR Notify N.M.O.C.C. in sufficient time to witness DATE OCT 2 1 1974