

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Alameda, NM 88210

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

AUG 10 8 04 AM '87

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR

Union Texas Petroleum Corporation

3. ADDRESS OF OPERATOR

4000 N. Big Spring, Suite 400, Midland, TEX 79705 BY

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)
See also space 17 below.)
At surface

2310' FNL & 990' FEL, Section 13

CARLSBAD RESURGE
AREA HEADQUARTERS

AUG 17 1987

O. C. D.

ARTESIA, OFFICE

14. PERMIT NO.

15. ELEVATIONS (Show water level, etc.)

3878' GL

5. LEASE DENOMINATION AND SERIAL
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
NM-12466-12828

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Shelby Federal

9. WELL NO.

1

10. FIELD AND POOL OR WILDCAT

McKittrick Hills (Atoka Strawn)

11. SEC., T., S., M., OR B.L. AND SURVEY OR AREA

Sec. 13, T22S, R24E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANT

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

P & A

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 8-1-87 Ran & Set CIBP @ 9346' - dump 3 sx cmt on CIBP to 9311'.
- 8-2-87 Set CIBP @ 9050'. Dump 3 sx "H" cmt from 9050 to 9015'
- 8-4-87 Cut csg @ 7190' & POH. Spot 150' plug from 7275 to 7125 w/25 sx cmt.
- 8-6-87 POH to 5650. Set 150' plug from 5650 to 5500' w/60 sx cmt.
PUH to 3550'. Set 100' plug from 3550 to 3450 w/40 sx cmt.
PUH to 1770'. Set 300' plug from 1770 to 1470 w/90 sx cmt.
Set plug from 500' to surface w/135 sx cmt.
- 8-7-87 Filled in cellar, weld cap on well & install dry hole marker.
Well now P&A.

Post ID-2
9-2-88
P & A

18. I hereby certify that the foregoing is true and correct

SIGNED

Ben White

TITLE

Reg. Permit Coord.

DATE

8-7-87

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

DATE

AUG 13 1987

*See Instructions on Reverse Side

SJS
CARLSBAD, NEW MEXICO