			Capt 10 2
Гогт 9-331 Мау 1963) DEP	ART ENT OF THE INTER!	SUBMIT IN T LICA' (Other instructive? on verse side)	TE* Form approved.
		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS			
(Do not use this form for Use "A	proposals to drill or to deepen or plug b PPLICATION FOR PERMIT—" for such pr	ack to a different reservoir. coposals.)	
		-	7. UNIT AGREEMENT NAME-
OIL GAS WELL OT	THER		· 영상에도 도 도 수 목장립
NAME OF OPERATOR	/		8. FABM OR LEASE NAME -
Marathon Oil Company			Federal Gas-"Com"
ADDRESS OF OPERATOR		·····	9. WELL NO.
P. O. Bo	x 220, Hobbs, New Mexico	88240	
LOCATION OF WELL (Report loc	cation clearly and in accordance with any	State requirements.*	10. FIELD AND POOL, OR WIEDCAT
See also space 17 below.) At surface			Springs Upper Penn Gas
			11. SEC., T., B., M., OR BLIG AND
1849' FWL & 1919.2' FNL			SURVEY OR AZEA
			Sec. 3-21S-25E
4. PERMIT NO.	15. ELEVATIONS (Show whether DF,	, RT, GR, etc.)	12. COUNTY OB PARISH 18. STATE
	GL 3313.7'		Eddy New Mexico
3. Che	ck Appropriate Box To Indicate N	lature of Notice, Report, o	or Other Data & Book P
NOTICE OF	F INTENTION TO:	SUB	SEQUENT REPORT OF
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON®	SHOOTING OR ACIDIZING	ABANDONMENT* X
REPAIR WELL	CHANGE PLANS	(Other)	
(Other)		(NOTE: Report res	sults of multiple completion on Well ompletion Report and Log form.)
7. DESCRIBE PROPOSED OR COMPLE	TED OPERATIONS (Clearly state all pertinent	t details, and give pertinent d	ates, including estimated date of starting any
proposed work. If well is nent to this work.)*	directionally drilled, give subsurface locat	nons and measured and true ve	rtical depths for all markers and zoues orti-
Well drilled t	o 8350' TD. Finished tes	sting well 10-3-68.	දී මිනිම් සි රිංකිය ලී ම පමුළුම යි රිංකිය ලී
	to 8350' TD. Finished test of ended to plug and abar	-	. Went in hole
	o 8350' TD. Finished tes en ended to plug and abar	-	Went in hole
with drill pipe op	en ended to plug and abar	-	Went in hole and it.
with drill pipe op		-	Went in hole and it.
with drill pipe op	en ended to plug and abar ment plugs as follows:	-	Went in hole and it.
with drill pipe op Set 50 sack ce	en ended to plug and abar ment plugs as follows: 1 8220' - 8120'	-	Went in hole and it.
with drill pipe op Set 50 sack ce Plug No.	en ended to plug and abar ment plugs as follows: 1 8220' - 8120' 2 6620' - 6500'	-	Went in hole and it.
with drill pipe op Set 50 sack ce Plug No. Plug No.	en ended to plug and abar ment plugs as follows: 1 8220' - 8120' 2 6620' - 6500' 3 5100' - 5000'	-	Went in hole and it.
with drill pipe op Set 50 sack ce Plug No. Plug No. Plug No. Plug No.	en ended to plug and abar ment plugs as follows: 1 8220' - 8120' 2 6620' - 6500' 3 5100' - 5000'	ndon.	Went in hole and it.
with drill pipe op Set 50 sack ce Plug No. Plug No. Plug No. Plug No.	en ended to plug and abar ment plugs as follows: 1 8220' - 8120' 2 6620' - 6500' 3 5100' - 5000' 4 2750' - 2650'	ndon.	Went in hole and it.
with drill pipe op Set 50 sack ce Plug No. Plug No. Plug No. Plug No. Set 15 s	en ended to plug and abar ement plugs as follows: 1 8220' - 8120' 2 6620' - 6500' 3 5100' - 5000' 4 2750' - 2650' ack plug in 8-5/8" casing	ndon. g at surface.	Went in hole and it.
with drill pipe op Set 50 sack ce Plug No. Plug No. Plug No. Plug No. Set 15 s	en ended to plug and abar ment plugs as follows: 1 8220' - 8120' 2 6620' - 6500' 3 5100' - 5000' 4 2750' - 2650'	ndon. g at surface.	Went in hole and it.
with drill pipe op Set 50 sack ce Plug No. Plug No. Plug No. Plug No. Set 15 s	en ended to plug and abar ement plugs as follows: 1 8220' - 8120' 2 6620' - 6500' 3 5100' - 5000' 4 2750' - 2650' ack plug in 8-5/8" casing	ndon. g at surface.	Went in hole is a set of the solution of the s
with drill pipe op Set 50 sack ce Plug No. Plug No. Plug No. Plug No. Set 15 s	en ended to plug and abar ement plugs as follows: 1 8220' - 8120' 2 6620' - 6500' 3 5100' - 5000' 4 2750' - 2650' ack plug in 8-5/8" casing	ndon. g at surface.	Went in hole and it.
with drill pipe op Set 50 sack ce Plug No. Plug No. Plug No. Plug No. Set 15 s	en ended to plug and abar ement plugs as follows: 1 8220' - 8120' 2 6620' - 6500' 3 5100' - 5000' 4 2750' - 2650' ack plug in 8-5/8" casing	ndon. g at surface.	Went in hole is the solution of the solution o
with drill pipe op Set 50 sack ce Plug No. Plug No. Plug No. Plug No. Set 15 s	en ended to plug and abar ement plugs as follows: 1 8220' - 8120' 2 6620' - 6500' 3 5100' - 5000' 4 2750' - 2650' ack plug in 8-5/8" casing	ndon. g at surface.	Went in hole is a set of the set
with drill pipe op Set 50 sack ce Plug No. Plug No. Plug No. Plug No. Set 15 s	en ended to plug and abar ement plugs as follows: 1 8220' - 8120' 2 6620' - 6500' 3 5100' - 5000' 4 2750' - 2650' ack plug in 8-5/8" casing	ndon. g at surface.	Went in hole is the solution of the solution o
with drill pipe op Set 50 sack ce Plug No. Plug No. Plug No. Plug No. Set 15 s	en ended to plug and abar ement plugs as follows: 1 8220' - 8120' 2 6620' - 6500' 3 5100' - 5000' 4 2750' - 2650' ack plug in 8-5/8" casing	ndon. g at surface.	Went in hole is a solution of the solution of
with drill pipe op Set 50 sack ce Plug No. Plug No. Plug No. Set 15 s Installed perm	en ended to plug and abar ment plugs as follows: 1 8220' - 8120' 2 6620' - 6500' 3 5100' - 5000' 4 2750' - 2650' ack plug in 8-5/8" casing manent well marker four fo	ndon. g at surface.	Went in hole is the solution of the solution o
with drill pipe op Set 50 sack ce Plug No. Plug No. Plug No. Set 15 s Installed perm	en ended to plug and abar ment plugs as follows: 1 8220' - 8120' 2 6620' - 6500' 3 5100' - 5000' 4 2750' - 2650' ack plug in 8-5/8" casing manent well marker four fo	ndon. g at surface. eet above ground.	Went in hole is a second of the solution of th
with drill pipe op Set 50 sack ce Plug No. Plug No. Plug No. Set 15 s Installed perm	en ended to plug and abar ment plugs as follows: 1 8220' - 8120' 2 6620' - 6500' 3 5100' - 5000' 4 2750' - 2650' ack plug in 8-5/8" casing manent well marker four fo	ndon. g at surface.	Went in hole is a solution of the solution of
with drill pipe op Set 50 sack ce Plug No. Plug No. Plug No. Set 15 s Installed perm	en ended to plug and abar ment plugs as follows: 1 8220' - 8120' 2 6620' - 6500' 3 5100' - 5000' 4 2750' - 2650' ack plug in 8-5/8" casing manent well marker four for solution for the second	ndon. g at surface. eet above ground.	
with drill pipe op Set 50 sack ce Plug No. Plug No. Plug No. Plug No. Set 15 s Installed perm S. I hereby certify that the fore SIGNED	en ended to plug and abar ment plugs as follows: 1 8220' - 8120' 2 6620' - 6500' 3 5100' - 5000' 4 2750' - 2650' ack plug in 8-5/8" casing manent well marker four for manent well marker four for tate office use)	ndon. g at surface. eet above ground.	
with drill pipe op Set 50 sack ce Plug No. Plug No. Plug No. Set 15 s Installed perm 8. I hereby certify that the fore SIGNED	en ended to plug and abar ment plugs as follows: 1 8220' - 8120' 2 6620' - 6500' 3 5100' - 5000' 4 2750' - 2650' ack plug in 8-5/8" casing hanent well marker four for marker four for tate office use) 	ndon. g at surface. eet above ground.	
with drill pipe op Set 50 sack ce Plug No. Plug No. Plug No. Set 15 s Installed perm 8. I hereby certify that the fore SIGNED	en ended to plug and abar ment plugs as follows: 1 8220' - 8120' 2 6620' - 6500' 3 5100' - 5000' 4 2750' - 2650' ack plug in 8-5/8" casing manent well marker four for manent well marker four for tate office use)	ndon. g at surface. eet above ground.	
with drill pipe op Set 50 sack ce Plug No. Plug No. Plug No. Set 15 s Installed perm 8. I hereby certify that the fore SIGNED	en ended to plug and abar ment plugs as follows: 1 8220' - 8120' 2 6620' - 6500' 3 5100' - 5000' 4 2750' - 2650' ack plug in 8-5/8" casing hanent well marker four for marker four for tate office use) 	ndon. g at surface. eet above ground.	Went in hole and a sub-transformed with the source of the sub-transformed and the sub-transformed sub-transfor

Dist. CoPL; LHS; BGH; Gulf; Atlantic Fichfield (2); Cities Service; Phillips; Hanson; File

.