

NO. OF COPIES RECEIVED	17
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FEB 9 1971

O. C. C.

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
K-3268-1

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	Catclaw Draw Unit
Hanagan Petroleum Corporation	8. Farm or Lease Name
3. Address of Operator	Catclaw Draw Unit
P. O. Box 1737, Roswell, New Mexico 88201	9. Well No.
4. Location of Well	1
UNIT LETTER F, 1980 FEET FROM THE North LINE AND 2310 FEET FROM	10. Field and Pool, or Wildcat
THE West LINE, SECTION 26 TOWNSHIP 21S RANGE 25E NMPM.	Wildcat
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3399 GR	Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/28/71: Spud 4:00 P.M. with cable tools - Fred Pool Contractor

Propose to drill 500' to 600' of 16" hole with cable tools, set 13-3/8" conductor and move rotary rig in.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Hugh C. Hanagan</u>	TITLE <u>Vice-President</u>	DATE <u>2/8/71</u>
APPROVED BY <u>W. A. Gressett</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>FEB 9 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		