

COPIES RECEIVED	
TRIBUTION	
FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

N: M: O: C: C: COM

U.S.G.S. RECEIVED  
NEW MEXICO OIL CONSERVATION COMMISSION

Copy to SF

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

NOV 22 1978

O. C. C.  
ARTESIA, OFFICE

5a. Indicate Type of Lease State <input type="checkbox"/> Fed <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. NM 7116

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator El Paso Natural Gas Company	8. Farm or Lease Name Rocky Arroyo "B" Corn.
3. Address of Operator 1800 Wilco Building Midland, TX 79701	9. Well No. 1
4. Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 17 TOWNSHIP 22-S RANGE 22-E NMPM.	10. Field and Pool, or Wildcat Rocky Arroyo Morrow
15. Elevation (Show whether DF, RT, GR, etc.) 4374' GR	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

SUBSEQUENT REPORT OF:  
REMEDIAL WORK ☐  
COMMENCE DRILLING ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MOL and RUPU. Set BOP. TOHw/tbg.
- TIH to 9050' and load hole w/gelled mud. Spot 25 sx Cl H cmt 9050'-8850' and displace w/mud. Pull 48 stds to 6000'. WOC.
- Tag plug w/tbg. TOH to 7400' and spot 25 Cl H cmt 7400-7200'. Disp w/mud. TOH and WOC.
- Tag t/cmt w/sand line. RU spear and determine freepoint of 5½" csg. Cut braidenhead 3' below GL.
- Cut csg and pull and LD.
- TIH w/tbg and spot 12 sx Cl C 50' below stub. TOH and spot 12 sx Cl C 1940-1830'. TOH and spot 100' surf plug.
- Weld on plate and P&A marker. Clean location for inspection. Estimated starting date: NA

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. I. Port Jr. TITLE Production Engineer DATE 10/17/78

APPROVED BY Joe S. Lora TITLE ACTING DISTRICT ENGINEER DATE NOV 21 1978  
CONDITIONS OF APPROVAL, IF ANY: