

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

JAN 27 1976

O. C. C.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-1898	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Plug & Abandon</u>		7. Unit Agreement Name Catclaw Draw Unit
2. Name of Operator Hanagan Petroleum Corporation		8. Farm or Lease Name Catclaw Draw Unit
3. Address of Operator P. O. Box 1737 Roswell, New Mexico 88201		9. Well No. 3
4. Location of Well UNIT LETTER <u>D</u> <u>920</u> FEET FROM THE <u>North</u> LINE AND <u>920</u> FEET FROM THE <u>West</u> LINE, SECTION <u>36</u> TOWNSHIP <u>21S</u> RANGE <u>25E</u> NMPM.		10. Field and Pool, or Wildcat Catclaw Draw Morrow & Stra
15. Elevation (Show whether DF, RT, GR, etc.) 3480 KB		12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/24/76: P.B.T.D. 10,410', plug & abandonment w/tubing in this manner w/Baber Cementing shot 5½" casing off @ 8612'.

Set Plugs: 1 - 35 sx. plug Class "C" from 8560 to 8660 in & out stub of 5½" csg.
1 - 35 sx. plug 8000-8100'
1 - 35 sx. plug 6250-6350'
1 - 35 sx. plug 4340-4400'
1 - 35 sx. plug 2080-2180' in & out 8-5/8" csg.
1 - 10 sx. plug @ surface w/appropriate dry hole marker

Mud Gel between all plugs

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M.L. Southerland TITLE Agent DATE 1/26/76

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: