

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

JAN 8 1976

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-1898	

SUNDRY NOTICES AND REPORTS ON WELLS

O. C. C.

ARTESIA OFFICE

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- Plug & Abandon		7. Unit Agreement Name Catclaw Draw Unit
2. Name of Operator Hanagan Petroleum Corporation ✓		8. Farm or Lease Name Catclaw Draw Unit
3. Address of Operator P. O. Box 1737 Roswell, New Mexico 88201		9. Well No. 3
4. Location of Well UNIT LETTER D, 920 FEET FROM THE North LINE AND 920 FEET FROM THE West LINE, SECTION 36 TOWNSHIP 21S RANGE 25E NMPM.		10. Field and Pool, or Wildcat Catclaw Draw Morrow&Strawn
15. Elevation (Show whether DF, RT, GR, etc.) 3480 KB		12. County Eddy

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to plug & abandon subject well as discussed by phone with Mr. Gressett. Orig. T.D. 10,930, present P.B.T.D. 10,410' (Morrow perms. sqzd. off), present perms. (4 holes) in Strawn 9546-56 top cmt. by temp. survey 9000'. Plan to salvage as much 5½" csg. as possible above 9000', will fill csg. with heavy drilling mud plus uncased part of hole, 8-5/8" csg. set @ 2130' w/7-7/8" hole to total depth. Set plugs as follows (35 sx.): 50' in & out stub of 5½" csg., 8000-8100, 6250-6350, 4340-4440 & in & out 8-5/8" csg. 2080-2180, 10 sx. plug @ surface w/appropriate dry hole marker. Work to be performed next week.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Hugh C. Hanagan TITLE Vice President DATE 1/7/76

APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE JAN 13 1976

CONDITIONS OF APPROVAL, IF ANY: Notify N.M.O.C.C. in sufficient time to witness.

Plugging after 5½" csg. recovered