

State "y"

1

TD 1 945'

12-30-72 ru 1-2-73 WOCU.
CORRECTEL EPORT 12-27-72 Casing Program
Down on landing joint 13.18
93 jts 11.6# N-L 3011.31
129 jts 11.6# K-S 4249.06
21 jts 11.6# N-L 680.42
Howco DVT 2.75
T/7953.90
85 jts 11.6# N-L 2769.86
36 jts 13.5# N-L 1182.70
Howco differential float collar 1.71
T/11,909.21
1 jt 13.5# N-L shoe jt 33.26
Howco guide shoe .75
CASING DEPTH 11,945.00'
Bottom 725.60' had been sandblasted in yard.
1 centralizer on shoe jt, 2nd jt & every
64' for a total of 12 centralizers on 1st
stage. 1 Howco basket each above and below
DVT. 1 centralizer below DVT & on 1st jt
above, then every 64' for a total of 13
centralizers on 2nd stage.
Note: When temp survey run by Bennett W.L.
Surveys, some kind of bridge was found @
6928' w/the 1 1/4" temp device.