

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPI
(Other instructions
reverse side)

TE
re

Form approved.
Budget Bureau No. 1004-001
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-65387

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back a well or reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR
INDREX, Inc.
3. ADDRESS OF OPERATOR
7633 E. 63rd Place, Suite 500, Tulsa, Oklahoma 74132
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

MAY - 8 '89

O. C. D.
ARTESIA, OFFICE

1980' FNL & 660' FEL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Four Forks Federal

9. WELL NO.

1

10. FIELD AND POOL OR WILDCAT

Artesia Mesa BS

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 15, T-22-S, R-25-E

12. COUNTY OR PARISH

13. STATE

Eddy

New Mexico

14. PERMIT NO.

NM-65387

15. ELEVATIONS (Show whether DF, RT, GK, etc.)

3471 Gr

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The captioned well is to be abandoned as uneconomical.

1. Pull production equipment.
2. Set CIBP @ 4300' & cap w/35' cement.
3. Free point, cut and lay down 5-1/12" casing from 1200'.
4. RIH w/2-3/8" tbg & displace hole w/9.5 ppg mud laden fluid.
5. Spot 100' cement plug @ 2225'.
6. Spot 100' cement plug @ csg stub.
7. Spot 100' cement plug @ 540'.
8. Spot 50' cement plug @ surf.
9. Cut off heads. Clean location.

RECEIVED
MAY 11 10 15 AM '89

18. I hereby certify that the foregoing is true and correct

SIGNED

Mickey Dolan

TITLE

Agent for INDREX, Inc.

DATE

4-28-89

(This space for Federal or State office use)

APPROVED BY

[Signature]

TITLE

FOR: CHIEF, MINERAL RESOURCES

DATE


5-3-89

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

INDREX/OGS AREA OF MAJOR CONCERN TO CARLSBAD WATER WELL RECHARGE]
 WELL: Four Forks Federal #1 LEASE NO. NM-65387
 LOCATION: SENE of Sec. 15, T22S, R25E, N10E1M
 [CARLSBAD WATER BASIN]

P&A PROPOSAL
 SJSshaw 4/26/89



*NOTE: Use 9.5 lb/gal mud-laden fluid between plugs.