.*	Bureau of Land Management Roswell, New Mexico
Lease No	NN - 7068
Operator	Monsanto
Well Name	1-Miller Fed.
Sec	3 I. 21 R. 27
Footage	1600/N 1980/E
	"STANDARD <u>ABANDOWENT</u> STIPULATIONS FOR ALL DRILLING IN RELATION TO OIL AND GAS ACTIVITIES IN THE <u>ROSWELL DISTRICT</u> "
abandonment eastern New lations appl	ing list of 5 stipulations are some of the more commonly used stipulations for oil and gas drilling operations in south- Mexico. The blocks checkmarked in red designate the stipu- licable to the particular abandonment notice listed above. additional stipulations (if any) are written in under #6.)
	ne surface location is to be cleaned <b>all approa</b> d as per S.G.S. requirements.
C op	vivate Surface: Abandonment stipulations to coincide with perator-landowner agreement. (Where no agreement exists, ne BLM will be contacted to provide abandonment stipulations.)
	ne drill pad and _/000 miles of access road should be pped to a minimum of 12" in depth.
of K-1	ne drill site (including reserve pit area) and <u>1000</u> <del>tiles</del> access road should be reseeded according to the attached accommendations.
tc tc sp	I ripped surfaces are to be protected from vehicular travel by onstructing a dead-end ditch and earthen barricade at the entrance o these ripped areas. The barricade is to be constructed using poil material from the ditch and should be of sufficient mag- tude to discourage vehicle entry.
6. s <sub>p</sub>	Recontour pad Production facilities stilledact.

•

----

----

7-78

-