Big Eddy No. 35 Dos Hermanos/Morrow 5-20-78 - Drilled 2206'-2248' w 7 7/8" bit Got thumbnail size steel POH LD 7 7/8" bit & casing scraper RIH w 6 1/4" bit ١ Drilled 2248-2266' Power swivel brokedown SDON TOTAL COST \$31,890 5-21-78 - Drilled cement 2266'-2355' @ 2275' fell through 2275-2355 stringers only POH & PU 7 7/8" OD string mill w/one dc below RIH Milled thru something 1" long @ 2200' (DV Tool). Went down to 2235' hit bad casing Reamed 2235-41 (1 1/2 - 2 hrs.) Reamed back to 2355'. Circ. OK. Pulled up to 2000'. Swung. Số for Sunday. TOTAL COST \$33,900

Big Eddy No. 35 Dos Hermanos/Morrow

5-23-78 - RIH w/mill to 2260' free. POH, LD mill. RIH w/retrieving tool, washed 20' of sand and cement off BP. Latched BP and POH. PU 7 7/8" bit and 4 3/4" dc and RIH. Drilled cement 3837' to 3867'. 1-2 min/ft.

SDON.

TOTAL COST \$36,000

Big Eddy No. 35 Dos Hermanos/Morrow

5-24-78 - Drilled out cement from 3867' to 4090'. Circulated hole clean with fresh water. Pulled up into casing. SDON.

TOTAL COST \$37,900