SHOOT OR ACIDIZE

REPAIR WELL

(Other)

TED STATES SUBMIT IN THE ICATE* Other instructions on reverse side)

SHOOTING OR ACIDIZING

(Other) _

Spud

5. LEASE DESIGNATION AND BL.

ABANDON MENT*

316

GEOLOGICAL SURVEY

ABANDON*

CHANGE PLANS

OLOLOGICAL SOLVE!	WA 0014020	
SUNDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE O.	

	Use "APPLICA	TION FOR PERMIT-" for such r	THE TYPE D	
1.	OIL GAS OTHER		*	7. UNIT AGREEMENT N.M.
2	NAME OF OPERATOR		1973	8. FARM OR LEASE NAME
	HANAGAN PETROLEUM COR	PORATION ~		Happy Vailey
3.	ADDRESS OF OPERATOR		D. C. C.	9. WELL NO.
	P. O. Box 1737, Roswe	11, New Mexico 88201		1
4.	LOCATION OF WELL (Report location of See also space 17 below.) At surface			Wildcat 11. SEC., T., R., M., OA BLK. AND SURVEY OR AREA
	700' FNL &	660' FEL		9-22 S -26E
14.	PERMIT NO.	15. ELEVATIONS (Show whether DF	RT, GR, etc.)	12. COUNTY OR PARISH 13. STA
		3327' GR		Eddy
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data			
	NOTICE OF INTENTION TO:			EQUENT REPORT OF:
		PULL OR ALTER CASING MULTIPLE COMPLETE	WATER SHUT-OFF FRACTURE TREATMENT	REPAIRING WELL ALTERING CASING

(Note: Report results of multiple completion : Well Completion or Recompletion Report and Log form : 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of state proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zon nent to this work.) •

Spud 11:00 AM, $3/\frac{29}{73}$ - Clyde Tidwell - Cable Tools. Set 10' 16" 42# casing cemented w/ready mix. Reamed 10" hole out to $12\frac{1}{4}$ " to 93'. Ran 3 jts. 40.5# J55 ST&C, mudded in at 93', comp. at 6:30 PM, 3/29/73.

18. I hereby certify that the foregoing is true and correct SIGNED / LUGAR / Tours der	Vice President	DATE 3/30/73
(This space for Federal or State office visc	DISTRICT ENGINEER	APR 2 1973
APPROVED BY	TITLE	DATE