

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TR. DATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0331649A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal "L"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Elisbad South

SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

34-22S-26E

12. COUNTY OR PARISH 13. STATE

Eddy

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Midwest Oil Corporation ✓

3. ADDRESS OF OPERATOR

1500 Wilco Building

Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.)

At surface

1980' FSL & 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

Gr. 3310.5

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10-23-73 CP 200. Blew well down immed. RU 8" BOP. Ran spear into 4½" csg. POH w/8 jts & cut off jt (approx 300' csg.) RIH w/OS could not get over csg stub looking up. RIH w/spear; caught fish and unscrewed csg. POH w/7 jts (approx 250'). Ran 7 stands tbg IH.

10-25-73 WO csg. Bradenhead press 400. Blew well down. P 100 bbls 10% brine wtr. POH w/tbg. RIH w/special skirted collar and 537' 4½" csg; screwed back onto csg; pld 23,000# and closed BOP around csg, set temporary slips. RU second BOP on T/csg. RIH w/on-off tool and latched onto pkr at 628'. RU WL tools; pld plg f/pkr.

10-26-73 TP 100, CP 0. Bradenhead flaring to pits. POH w/pkr and tbg. PU on 4½" csg LD 8' sub; set csg on temporary slips w/97,000# tension. RIH w/spear and tried to get into tbg. Made second rn w/new spear and latched onto tbg @ 660'. POH w/tbg and spear that was left IH the 19th. RIH w/spear and caught tbg @ 1000'. Pld and worked pipe to 70,000#; could not rel on-off tool @ 11,232'. POH w/tbg. LD spear. Tbg stretch indicates tbg stuck @ 8300. P/rn free pt. and cut off.

10-27-73 TP 0, CP 0, Bradenhead press 600#. RIH w/OS and caught tbg at 1000'. POH
(Continued on Page 2)

18. I hereby certify that the foregoing is true and correct

SIGNED

Bonnie Husband

TITLE

Production Clerk

DATE

11-9-73

(This space for Federal or State office use)

TITLE

DATE

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side