				Ca	ey 6.5F	
	Point 9-341 (May 1963) (Other Instructions on re- DEPARTMENT OF THE INTERIOR Verse side) GEOLOGICAL SURVEY			FORM ADDROVED Hudget Burean No. 42 K1424 5, LEARE DERIGNATION AND MERIAL NO NM-14768 6, IF INDIAN, ALLOTTEE OR TRIME NAME		
	SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)					
1. 011. WE	U GAS OTHER	7. UNIT AGREEMENT N				
2. NA)	IE OF OPERATOR	8. FARM OR LEASE NAME				
Gul	f Oil Corporation $ u$	Cerf Federal Com				
	RESS OF OPERATOR	9. WELL NO.				
Boy	670, Hobbs, New Mer	1				
4. LOC	ATION OF WELL (Report location c	10. FIELD AND POOL, OR WILDCAT				
	also space 17 below.) surface	Burton Flat Strawn & Morro				
	FNL & 1980' FWL, Section 10, 21-S, 27-E				11. SEC., T., R., M., OR BLK. AND SUBVEX OR AREA	
560' FNL					•	
			Sec 10, 21-	S 27-F		
	4. PERMIT NO. 15. ELEVATIONS (Show whether		RT. 0R. etc.)	12. COUNTY OR PARIS	H 13. STATE	
14. PE	IMIT NO.			T 1 1	New Mexico	
		321	7' GL	Eddy	I NEW MEXICO	
16,	6. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data					
				ENT REPORT OF:		
				7		
ויד	ST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING		
Fl	ACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT XX	X ALTERING		
s	HOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING XX	ABANDONMI	ENT -	
RI	PAIR WELL	CHANGE PLANS	(Other)	of multiple completion	on Well	
()	(Other) Completion or Recompl		letion Report and Log I	orm.)		
17. DE	SCRIBE PROPOSED OR COMPLETED OPI	IRATIONS (Clearly state all pertinen	t details, and give pertinent dates,	including estimated da	te of starting any	

proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical nent to this work.) \bullet

11,515' TD, 11,473' PB.

Pulled producing equipment. Cleaned out to 11,473'. Perforated Strawn zone in 7" casing with 4 JHPF at 10,216-22', 10,250-56' & 10,264-70'. Ran treating equipment and treated new perforations with 250 gallons of 15% NE acid and 9,000 gallons of 7-1/2% acid and 24,000 gallons containing 1/2# to 2# SPG. Maximum pressure 7950#, ISIP 5,000#, after 15 minutes 4700#. Swabbed and cleaned up. Pulled treating equipment. Perforated Morrow zone in 7" casing with 4, 1/2" JHPF at 11,273-81', 11,332-36', 11,339-44' and 11,352-62'. Ran Otis XLB packer on wire line and set at 10,925'. Ran long string of 2-7/8" tubing and Otis RDA packer. Latched into XLB packer at 10,925' and set RDA packer at 10,109'. Set tubing with 15,000# compression. Ran short string of 2-3/8" tubing and set in RDA packer at 10,109'. Swabbed and cleaned up both zones. Closed well in pending FPC approval to produce.

• •	REDEIVED	•	
	Jan 6 1975	• • •	
	O. C. C. ARTESIA, OFFICE		U.S. GEOLOCIEVI MILITI MITESIA, TIEVI MILITI
18. I hereby certify that the foregoing is true and correct SIGNED	TITLE Area Engineer		
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE		DATE
Ail 5 June 19 DEEKINATIER INSTRUCT ENGINEER	ee Instructions on Reverse Side	•	