

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input type="checkbox"/>
LAND OFFICE	<input type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

RECEIVED BY FAX  
DEC - 2 1985  
O. C. D.  
BOX 2088  
NEW MEXICO 87501

5a. Indicate Type of Lease  
State ☒ For ☐  
5. State Oil & Gas Lease No.  
V 231

SUNDRY NOTICES, REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Anadarko Petroleum Corporation	8. Farm or Lease Name Sun State
3. Address of Operator P. O. Drawer 130, Artesia, New Mexico 88210	9. Well No. 1
4. Location of Well UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 22 TOWNSHIP 21S RANGE 27E NMPM.	10. Field and Pool, or Wildcat Delaware Wildcat
11. Elevation (Show whether DF, RT, GR, etc.) 3244.8' GL	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐  
PLUG AND ABANDON ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up pulling unit. Tripped out of hole with rods.
2. Circulated hole with 10# brine and salt gel mud.
3. Spotted 50 sx Class H with 4% CaCl from 3150' up to 2970'. Pulled up hole and waited 3 hours. Tagged top of plug at 3010'. (This plug covers 8-5/8" casing shoe)
4. Spotted 50 sx Class H with 4% CaCl from 2730' up to 2550'. Pulled up hole and waited 3 hours. Tagged top of plug at 2570'. (This plug covers Delaware top)
5. Spotted 50 sx Class H with 4% CaCl from 470' up to 320'. Pulled up hole and waited 3 hours. Tagged top of plug at 320'. (This plug covers 13-3/8" casing shoe)
6. Spotted 60' surface plug.
7. Cut off all casing and anchors below surface; set P & A marker; cleaned and leveled location.

NOTE: There is 10# brine and salt gel mud between all plugs.

Post ID-2  
12-13-85  
PVA

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mike Brumfield TITLE Field Foreman DATE Nov. 27, 1985

APPROVED BY Danell Moore TITLE Geologist DATE 5/24/89

CONDITIONS OF APPROVAL, IF ANY: