

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

C CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO.
30-015-20838

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

K-3977

7. Lease Name or Unit Agreement Name

Yates State

8. Well No.

1

9. Pool name or Wildcat

Burton Flat (Morrow); gas

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

Unit Petroleum Company

3. Address of Operator

P.O. Box 702500, Tulsa, OK 74170-2500

4. Well Location

Unit Letter K : 1,980 Feet From The south Line and 1,980 Feet From The west Line

Section 10

Township 21S

Range 27E

NMPM Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3,275'-KB Datum

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Release pkr at 11,195'. Circ hole w/plug mud. Pull out of hole w/tbg.
- 2) Set 7" CiBP at 11,200'. Dump bail 35' cement on top.
- 3) Find freepoint of 7" csg and shoot off as deep as possible (TOC at 9,540'). Pull out of hole w/csg.
- 4) Spot 100' cement plugs as follows:
 - A) across 7" csg stub (50' above and below)
 - B) at 7,500'
 - C) at 5,165' (Bone Springs top)
 - D) across 9-5/8" csg shoe at 2,970'. (50' above and below) This plug will be tagged by wireline or tbg.
 - E) across 13-3/8" csg shoe at 611' (50' above and below) This plug will be tagged by wireline or tbg.
- 5) Top plug from 10' B.G.L. to surface
- 6) Cut off and weld on ID plate

NOTE: Work to begin upon approval

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Brent A. Keys

TITLE Production Engineer

DATE 12/9/97

TYPE OR PRINT NAME

Brent Keys

TELEPHONE NO.

(918) 493-7700

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

APPROVED BY

TITLE

DATE

JAN 26 1998

CONDITIONS OF APPROVAL, IF ANY: