NO. OF COPIES RECEIVED	3				Form C-103	
DISTRIBUTION					Supersedes Old	
SANTA FE	/N	EW MEXICO OIL CONS	SERVAFION OF	D BOLKING	C-102 and C-10 Effective 1-1-65	
FILE	14					
U.S.G.S.			ALIG 3	0 1973	5a. Indicate Type o	of Lease
LAND OFFICE				~ 1973	State X	Fee
OPERATOR			0. c	: C	5. State Oil & Gas K=5090	Lease No.
······	SUNDRY NOTICE				100000	mmm.
(DO NOT USE THIS FORM USE **						
1.					7. Unit Agreement	Name
OIL GAS WELL WELL	N/A					
2. Name of Operator	8. Farm or Lease t	8. Farm or Lease Name				
Hillin Production	JCW State	JCW State Com.				
3. Address of Operator	9. Well No.	9. Well No.				
P.O. Box 2889 -	2					
4. Location of Well	10. Field and Pool					
UNIT LETTER K 1980 FEET FROM THE West LINE AND 1980 FEET FROM					Und. Winches	ter Morrow
6	<u>^</u>					7/////////
THE South	E, SECTION	TOWNSHIP	IS RANGE	28E NMPM	• ())))))))	
						,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
15. Elevation (Show whether DF, RT, GR, etc.)					12. County	A////////X
	<i></i>	3275 GL		· · · · · · · · · · · · · · · · · · ·	Eddy	7//////////////////////////////////////
C	Check Appropriate	e Box To Indicate N TO:	lature of Not	-	ther Data	
PERFORM REMEDIAL WORK		PLUG AND ABANDON	REMEDIAL WOR	к [ALTERIN	G CASING
TEMPORARILY ABANDON			COMMENCE DRI	LLING OPNS. 🔀	PLUG AND	ABANDONMENT
PULL OR ALTER CASING		CHANGE PLANS	CASING TEST A	ND CEMENT JOB 🔀		
			OTHER			
OTHER	· · · · · · · · · · · · · · · · · · ·					
17. Describe Proposed or Comp work) SEE BULE 1103.	pleted Operations (Clea	rly state all pertinent det	ails, and give pe	rtinent dates, includin	g estimated date of sta	arting any proposed
Spud - August 9,						
Drill 17 1/2" ho						
w/47. gel & 27. ca						
cement & filled	hole to surfac	:e. W.O.C. 18 H	nrs Nipp	ple up - Test	csg. w/1000#	- 30 min.
0.K.						
Drilled 12 1/4"						
2116' = 24# = 8	5/8" - JS csg.	, - Total 2951'	to 2941 •	 cement w/ 25 	50 sx. class '	'C" w/4% gel
& 2% cal. chloride, Plug down 5:45 a.m 8-15-73. Ran temp. survey - Top of cement @ 1600						
outside 8 5/8", W.O.C. 18 hrs. Nipple up - Test ALL B.O.P. equipment, Hydrill, & choke man-						
ifold to 2000# - 0.K. Install flow meter & gas analyzer @ 9000' - displace hole w/9.5 & 10# K.C.L. brine water as						
	er & gas analy	/zer @ 9000' - d	i splace he	ble $w/9.5 \& 10$)# K.C.L. brin	ie water as
needed & drill.						

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. M. Hillin	TITLE Operator	DATE 8-28-73	
APPROVED BY For Renderd Solesset	TITLE OIL AND GAS INSPECTOR	SEP 4 1973	