

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

APR 7 1975

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

O.C.C.
ARTESIA, OFFICE

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator Hillin Production Company ✓ 3. Address of Operator P. O. Box 152, Odessa, Texas, 79760 4. Location of Well UNIT LETTER K 1980 FEET FROM THE West LINE AND 1980 FEET FROM THE South LINE, SECTION 2 TOWNSHIP 20 S RANGE 28 E NMPM.	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> 5. State Oil & Gas Lease No. K 5090 7. Unit Agreement Name K 8. Farm or Lease Name JCW State Com 9. Well No. 2 10. Field and Pool, or Wildcat Winchester-Morrow 12. County Eddy
15. Elevation (Show whether DF, RT, GR, etc.)	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Blew well down to pit. Pumped 100 bbls. 10# brine down tbgs. to kill well. Unset packer & circulated hole w/230 bbls. 10# salt-water mud. Pulled tubing. Ran CIBP & set at 9100'. Dumped 20' cement on top of plug. Cut 5 1/2" csg. @ 6625'; pulled and laid down 5 1/2" csg. Ran tbgs. to 6675' & circ. w/10# mud. Spotted the following cement plugs: 35 sax. @ 6675'; 35 sax. @ 5700-5600; 35 sax. @ 4100-4000; 35 sax. @ 3000-2900'. Cut 8-5/8" csg. @ 829'; pulled & laid down 8-5/8". Ran tbgs. & circ. hole w/10# mud. Pumped 50 sax. cement plug 875-775'; 50 sax. plug 400-300'. Laid down tbgs. Cut-off well head. Placed 10 sax. surface plug. Installed marker for plugged well. Rig down & move off 3-26-75.

csg. left in hole - 13 3/8" - 346 -
8 5/8" - 829 to 2941
5 1/2" 6625 to 11235

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. M. Hillin TITLE Owner DATE 4/4/75

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: