

IS PRODUCED, SHUT WELL IN IMMEDIATELY.

10. ONCE WELL CEASES TO FLOW, UNSET PACKER AND POH. RIH AND CLEANOUT TO PBTD.
11. RIH WITH PRODUCTION AND ARTIFICIAL LIFT EQUIPMENT. RWTP. ND BOP'S. RD WSU.