

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPL
(Other instructions
reverse side)N. M. Form 5-311, Copy
Budget Bureau No. 42-R1424
5. LEASE DESIGNATION AND SERIAL NO.NM 0454228(2)
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. NAME OF OPERATOR Continental Oil Company		7. UNIT AGREEMENT NAME	
2. ADDRESS OF OPERATOR Box 460, Hobbs, N.M. 88240		8. FARM OR LEASE NAME Levors Federal	
3. LOCATION OF WELL (Report location clearly and in accordance with any State or Federal Survey. See instructions on reverse side.) 1650' FSL & 1650' FSL OF Sec. 2		9. WELL NO. 2	
4. FIELD AND FOOT OR WILDCAT CATCHW Draw		10. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 2, T-24S, R-25E	
11. PERMIT NO.		12. COUNTY OR PARISH El Paso	
13. ELEVATIONS (Show whether LF, RT, GR, etc.) 3252' GR		14. STATE N.M.	

RECEIVED

DEC 23 1976

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

RECEIVED

DEC 28 1976

15. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACURE TREAT	MULTIPLE COMPLETION	FRACURE TREATMENT	ALTERING CASING
DRIFT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
LINEAR WELL	CHANGE PLANS	(Other)	

(NOTE: Report results of multiple completion on Well Completion or Re-completion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work).*

The Levors Federal No. 2 was Producing at a Rate of approx. 1 mcf/d when a sudden influx of water occurred and the well ceased to flow. It is proposed to cut squeeze all R/S's, and Redrill from 10134' to 10145' or better. Pull R/S at 10134'. Set cut Retainer at 10205' & squeeze below Retainer w/ 50 lb class H cement and 2% CaCl₂. SPAT 5-10' cut on top of Retainer. Run Tbg open-ended to 10145' & SPAT 40 SX class H cement. From 9766' to 10145'. Pull Tbg to 9600' and Pressure Test to 2000 PSI. Pull out cut to 10145' & Pressure Test to 1000 PSI. Perf 10134-10145' w/ 43SPF. Swab well to Production.

18. SIGNATURE OF DISTRICT ENGINEER Th. A. [Signature]		TITLE Admin. Supv.		DATE 12-22-76	
19. SIGNATURE OF ACTING DISTRICT ENGINEER Joe L. [Signature]		TITLE ACTING DISTRICT ENGINEER		DATE DEC 27 1976	

*See Instructions on Reverse Side

USGS-5
ARTESIA, NM