

OIL & GAS
Drilling
Artesia, NM

45F

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐

2. NAME OF OPERATOR
TXO Production Corp.

3. ADDRESS OF OPERATOR
415 W. Wall, Ste. 900-Midland, TX 79703

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE:
AT TOP PROD. INTERVAL: 1980' FNL & 660' FWL
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☒
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☒
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☐

RECEIVED

AUG 01 '89

O. C. D.
ARTESIA OFFICE

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Move in & rig up pulling unit. Kill well w/2% KCL. ND wellhead. NU BOP. Release packer. TOH w/tubing & packer.
2. Rig up wireline. Set CIBP # 10,300' w/20' cement on top.
3. Rig up casing spear. Work casing off of slips. Run free-point and cut casing. (TOC bond @ 8570')
4. Pull out of hole w/casing. Inspect, drift and test casing on location.
5. Trip in hole w/tubing open-ended to 6100'. Spot 175 sxs plug f/6100' 5575'. Spot 150' across stub & TAG. SIS
6. Trip in hole w/7-7/8" bit & dress plug off to 5700'.
7. Trip in hole w/4-1/2" casing to 5700'. Centralize across Delaware pay. Cement casing back to approx. 2800'. WOC. TIP w/WL. Rn GR/CCL & perf 3320-3342' w/1 JSPF. TIH w/tubing & pkr. Set pkr @ ±3220'. Swb & test.
8. Acidize w/2000 gallons 15% NeFe w/clay & silt additives. Swb back load. Place well on production.

18. I hereby certify that the foregoing is true and correct

SIGNED Marta Carol Hardy TITLE Asst. Sec. DATE 7/19/89

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE For [Signature] DATE 7-31-89

CONDITIONS OF APPROVAL, IF ANY: