

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

JUN 07 1983

O. C. D.

ARTESIA, OFFICE

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator C & K PETROLEUM, INC. ✓		8. Farm or Lease Name Harold Olive Com.
3. Address of Operator P. O. Drawer 3546, Midland, Texas 79702		9. Well No. #1
4. Location of Well UNIT LETTER 0, 660' FEET FROM THE South LINE AND 1980' FEET FROM THE East LINE, SECTION 14 TOWNSHIP 22S RANGE 26E NMPM.		10. Field and Pool, or Wildcat S. Carlsbad W. Offshoot
15. Elevation (Show whether DF, RT, GR, etc.) 3188 GL		12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Commence plugging 2-2-83.

Plug #1: Set 7" CIBP @ 10,050'. Cmt w/35 sx to 9950'.

Plug #2: 9900' - 9800' w/35 sx cmt.

Plug #3: 8775' - 8675' w/35 sx cmt. Stuck tbg @ 7813'. Shot tbg off @ 7805'. Left 8' tbg stub & CIBP setting tools in hole @ 7805' - 7813'. Tagged.

Plug #4: 6847' - 6747' w/35 sx cmt. Free point 7" csg @ 5100'. Shot 7" csg @ 5138', unable to move, shot 4710', csg free. Pull csg. Cmt. 50' in/out & tagged.

Plug #5: 5171' - 5071' w/35 sx cmt.

Plug #6: 4675' - 4543' w/35 sx cmt, tagged. Cut off 9-5/8" @ 1,116'. Pulled 9-5/8" csg.

Plug #7: 2307' - 2207' w/35 sx cmt.

Plug #8: 1162' - 1054' w/50 sx cmt. Tagged.

Plug #9: 246' - 50' w/35 sx cmt. Circ cmt to surf. Cut off 13-3/8" csg flange, weld cap on stub, installed dry hole marker.

Plugging completed 3-01-83

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Carol DeLeon TITLE Sec. to Operations Mgr. DATE 3-04-83

APPROVED BY For Record Only TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: