

J.C. ^{DW}
WILLIAMSON & UNDERWOOD ETAL

from the outer boundaries of the Section

Lead
WILLIAMSON FEDERAL

Well No. **X1**

Section	Township	Range	County
J	9	20 SOUTH	29 EAST
			EDDY

Actual Location of Well:

1980	feet from the	SOUTH	line and	1980	feet from the	EAST	line
Ground Level Elev.	Producing Formation	Foot		Dedicated Acreage			
3280.7	Narrow <i>Flats</i>	<i>Well</i>		320			
		<i>Barton Flat</i>					

1. Outline the acreage dedicated to the subject well by colored pencil or hachure marks on the plat below.
2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty).
3. If more than one lease of different ownership is dedicated to the well, have the interests of all owners been consolidated by communitization, unitization, force-pooling, etc?

☐ Yes ☐ No If answer is "yes," type of consolidation _____


If answer is "no," list the owners and tract descriptions which have actually been consolidated. (Use reverse side of this form if necessary.) _____

No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced-pooling, or otherwise) or until a non-standard unit, eliminating such interests, has been approved by the Commission.

RECEIVED

OCT 28 1976

U. S. G. S.
ASTORIA, OREGON



CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief.

W. J. Underwood
PARTNER.

WILLIAMSON &
UNDERWOOD ETAL

I hereby certify that the well location shown on this plat was plotted from field notes of the survey by me or under my supervision and that the same is true and correct to the best of my knowledge and belief.

RECEIVED
FEB 13 1974
U. S. GEOLOGICAL SURVEY
ASTORIA, NEW MEXICO

Date Surveyed

FEBRUARY 6, 1974

Registered Professional Engineer
and/or Land Surveyor

John W. West

Certificate No.

676

330 880 90 1320 1850 1940 2310 2640 2900 3200 3500 3800 4100 4400 4700 5000 5300 5600 5900 6200 6500 6800 7100 7400 7700 8000 8300 8600 8900 9200 9500 9800 10100 10400 10700 11000 11300 11600 11900 12200 12500 12800 13100 13400 13700 14000 14300 14600 14900 15200 15500 15800 16100 16400 16700 17000 17300 17600 17900 18200 18500 18800 19100 19400 19700 20000