		. :m C-103
NO. O' COPIES RECEIVED		o persedes Old
DISTR BUTION	COME THE TICK COMMISSION	C-102 and C-103
	CONS RVATION COMMISSION	Effective 1-1-85
FILE		Sa. In trate Type of Line
U.S.G.S		
LAND FICE		
OPE OR /		5. State Cfl & Gas Lease No.
SUNDRY NOTICES AND REPOR	TS ON WELLS	
OD NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OF	P PLUS PACE TO A DIFFERENT RESERVOIR.	
USE "APPEICATION FOR PERMIT 2" (FORM COTOL)	TO COURT PROPOSITION	7. Unit Aureoment Elime
GAS X OTHER-	RECEIVED	
		0. Firm of Leane Hame
me of Operator	4070	Tracy A Com.
Cities Service Oil Company	APR - 1 1976	g, Well 1. u
3. Address of Operator		1
Box 1919 - Midland, Texas 79701		1
4. Location of Well	U. U. U.	La Huerta Il au
C 660 FEET FROM THE	orth LINE AND FECT FRO	Burton Flat Morrow
West 33 TOWNSHIP	21S RANGE 27E	
THE LINE, SECTION TOWNSHIP	RANGE	
	whether DF, RT, GE, etc.)	12. County
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	whether Dr., Kt., Gr., etc.,	Eddy
3135' GR		Eddy
16. Check Appropriate Box To Indi	cate Nature of Notice, Report or O	ther Data
NOTICE OF INTENTION TO:		IT REPORT OF:
NOTICE OF INTENTION TO:		
	• [	ALTERING CALLES
PERFORM REMEDIAL WORK PLUG AND ABAND		= 5
TEMPORARILY ABANDON	COMMENCE DRILLING OFNS.	PLUG AND ABAL FORMENT
PULL OR ALTER CASING CHANGE PLANS	CASING TEST AND CEMENT JOB	hala aquimmont [w
-	OTHER Change of down	hole equipment x
ATUER	assembly.	
OTHER		
17. Describe Proposed or Completed Operations (Clearly state all perto	nent details, and give pertinent dates, include	ne estimate la compressione any proposer
work) SEE RULE 1103.		
O.T.D. 11570' Shale & Lime OPBTD 11545'.	The down hole equipment as:	sembly has been changed
	The down hore equipment abo	ocupat had soon shangs a
as follows:		
		. 22 1 11
<ol> <li>MIRU pulling unit, released pack</li> </ol>	cers set @ 10084' and 11047'	and pulled packers and
tubing out of the hole.		
2. Redressed Baker seal assembly ar	nd Model AR-1 compression pa	cker.
	in the seel assembly in the	Model D nacker @ 11017!
3. Ran 2-7/8" OD tubing and set it	in the sear assembly in the	are with the exception of
and a Model AR-1 packer set @ 10	)004 (tubing exactly as ber	ore with the exception of
Model L sliding sleeve @ 110h3'	and 2 ported 1.8/ F seating	nipples set above and b
low the Baker Model AR-1 packer	set @ 10084' being left out	of the hole).
I. The Morrow zone in now flowing	through the tubing and not t	urongu tue castuk as Leb
ed on the original well complet:	ion report. (See down hole c	ompletion schematic)
ed out the otterner agar combres.	- ı	
		· ·
Straw-Jone TA - 2-13-26	/	•
19 Jane TH - 2-13-66	,	
Mico		the state of the s
<b>67</b>		
18. I hereby certify that the information above is true and complete to	the best . newledge and besier.	
18. I hereby certify that the information above is tide and complete to		
>' / //	Dogian Connection Manager	March 31, 1976
SIGNED	Region Operation Manager	Haron Jr 1710
1000		
	SUPERVISOR, DISTRICT II	APR - 6 1976
61 /1 Showers	SUPERVISOR BELLE	DATAPK - U 13/U
APPROVED BY	1 LE	
CONDITIONS OF APPROVAL, IF ANY:		